

Broadmoor

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Broadmoor	Cadiz 3000	R/R Conc SW 4"	5.00	4.00	2.22	SY	3001
Broadmoor	Cadiz 3000	HC Ramp @ Intersection	12.00	12.00	16.00	SY	Intersection at S. Derbigny
Broadmoor	Cadiz 3000	R/R Conc SW 4"	5.00	4.00	2.22	SY	Opposite 3030
Broadmoor	Cadiz 3000	R/R Conc SW 4"	5.00	4.00	2.22	SY	3029
Broadmoor	Cadiz 3000	R/R Conc SW 4"	5.00	4.00	2.22	SY	Intersection at S. Derbigny
Broadmoor	Cadiz 3000	R/R Conc Pvmt 8"	30.00	13.00	43.33	SY	Opposite 3030
Broadmoor	Cadiz 3000	R/R Conc SW 4"	16.00	4.00	7.11	SY	3001
Broadmoor	Cadiz 3000	R/R Conc Pvmt 8"	16.00	26.00	46.22	SY	3001
Broadmoor	Cadiz 3000	R/R Conc SW 4"	12.00	4.00	5.33	SY	3030
Broadmoor	Cadiz 3100	R/R Conc SW 4"	10.00	4.00	4.44	SY	3101
Broadmoor	Cadiz 3100	R/R Conc SW 4"	5.00	4.00	2.22	SY	3100
Broadmoor	Cadiz 3100	R/R Conc Pvmt 8"	32.00	13.00	46.22	SY	3100
Broadmoor	Cadiz 3100	R/R Conc SW 4"	4.00	4.00	1.78	SY	Intersection at S. Roman (Northwest corner)
Broadmoor	Cadiz 3100	R/R Conc DW 6"	5.00	4.00	2.22	SY	3114
Broadmoor	Cadiz 3100	R/R Conc SW 4"	15.00	4.00	6.67	SY	3123
Broadmoor	Cadiz 3100	R/R Conc SW 4"	3.00	4.00	1.33	SY	3126
Broadmoor	Cadiz 3100	HC Ramp @ Intersection	12.00	12.00	16.00	SY	3126
Broadmoor	Cadiz 3100	R/R Conc SW 4"	4.00	4.00	1.78	SY	3114
Broadmoor	Cadiz 3100	HC Ramp @ Intersection	12.00	12.00	16.00	SY	Intersection at S. Roman (Northwest corner)
Broadmoor	Cadiz 3100	R/R Conc Pvmt 8"	16.00	26.00	46.22	SY	3100
Broadmoor	Cadiz 3200	R/R Conc SW 4"	17.00	4.00	7.56	SY	3222
Broadmoor	Cadiz 3200	R/R Conc SW 4"	29.00	4.00	12.89	SY	3221
Broadmoor	Cadiz 3200	R/R Conc SW 4"	10.00	4.00	4.44	SY	3212
Broadmoor	Cadiz 3300	R/R Conc Pvmt 8"	46.00	26.00	132.89	SY	Intersection at S. Johnson
Broadmoor	Cadiz 3300	R/R Conc SW 4"	25.00	4.00	11.11	SY	3302
Broadmoor	Cadiz 3300	R/R Conc SW 4"	6.00	4.00	2.67	SY	3301
Broadmoor	Cadiz 3300	R/R Asph 5.5"	19.00	28.00	59.11	SY	Intersection at S. Galvez Eastbound
Broadmoor	Cadiz 3400	R/R Conc SW 4"	75.00	4.00	33.33	SY	3400
Broadmoor	Cadiz 3400	R/R Conc Pvmt 8"	23.00	13.00	33.22	SY	3400

Broadmoor

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Broadmoor	Cadiz 3400	R/R Conc SW 4"	25.00	4.00	11.11	SY	3402
Broadmoor	Cadiz 3400	R/R Conc SW 4"	30.00	4.00	13.33	SY	3401
Broadmoor	Cadiz 3500	R/R Curb	27.00	0.00	27.00	LF	3501
Broadmoor	Cadiz 3500	R/R Conc SW 4"	104.00	3.00	34.67	SY	3502
Broadmoor	Cadiz 3500	R/R Asph 5.5"	200.00	24.00	533.33	SY	Entire 3500 block (S. Galvez to S. Miro)
Broadmoor	Cadiz 3600	R/R Conc SW 4"	59.00	4.00	26.22	SY	3601
Broadmoor	Cadiz 3600	R/R Conc SW 4"	18.00	4.00	8.00	SY	3604
Broadmoor	Cadiz 3600	R/R Asph 5.5"	17.00	25.00	47.22	SY	Intersection at S. Tonti (Southwest Quad)
Broadmoor	Cadiz 3600	R/R Curb	42.00	0.00	42.00	LF	3615
Broadmoor	Cadiz 3600	R/R Asph 5.5"	61.00	12.00	81.33	SY	3606
Broadmoor	Cadiz 3600	R/R Curb	32.00	0.00	32.00	LF	3615
Broadmoor	Cadiz 3600	R/R Asph 5.5"	135.00	24.00	360.00	SY	3604
Broadmoor	Cadiz 3600	R/R Asph 5.5"	51.00	15.00	85.00	SY	3602
Broadmoor	Cadiz 3600	R/R Conc SW 4"	94.00	4.00	41.78	SY	Opposite 3615
Broadmoor	Cadiz 3600	R/R Curb	36.00	0.00	36.00	LF	Opposite 3615
Broadmoor	Cadiz 3700	R/R Conc DW 6"	12.00	3.00	4.00	SY	3725
Broadmoor	Cadiz 3700	R/R Curb	71.00	0.00	71.00	LF	Opposite 3706
Broadmoor	Cadiz 3700	R/R Asph 5.5"	118.00	21.00	275.33	SY	3712
Broadmoor	Cadiz 3700	R/R Asph 5.5"	27.00	13.00	39.00	SY	3725
Broadmoor	Cadiz 3700	R/R Asph 5.5"	30.00	26.00	86.67	SY	3725
Broadmoor	Cadiz 3700	R/R Asph 5.5"	26.00	26.00	75.11	SY	3719
Broadmoor	Cadiz 3700	R/R Asph 5.5"	37.00	13.00	53.44	SY	3711
Broadmoor	Cadiz 3700	R/R Asph 5.5"	32.00	26.00	92.44	SY	3701
Broadmoor	Cadiz 3700	R/R Conc SW 4"	14.00	4.00	6.22	SY	3725
Broadmoor	Cadiz 4200	R/R Asph 5.5"	203.00	23.00	518.78	SY	4200 to 4238
Broadmoor	Cadiz 4200	R/R Conc SW 4"	40.00	3.00	13.33	SY	4231
Broadmoor	Delachaise 3000	R/R Conc SW 4"	10.00	4.00	4.44	SY	3000
Broadmoor	Delachaise 3000	R/R Conc SW 4"	22.00	4.00	9.78	SY	Opposite 3018
Broadmoor	Delachaise 3000	R/R Conc SW 4"	12.00	4.00	5.33	SY	3035
Broadmoor	Delachaise 3000	R/R Asph 5.5"	30.00	3.00	10.00	SY	3015
Broadmoor	Delachaise 3000	R/R Conc SW 4"	27.00	4.00	12.00	SY	3008 to 3014
Broadmoor	Delachaise 3100	R/R Conc SW 4"	5.00	4.00	2.22	SY	3129
Broadmoor	Delachaise 3100	R/R Conc SW 4"	19.00	4.00	8.44	SY	3114

Broadmoor

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Broadmoor	Delachaise 3100	R/R Conc SW 4"	56.00	4.00	24.89	SY	3115 to 3125
Broadmoor	Delachaise 3200	R/R Conc SW 4"	15.00	4.00	6.67	SY	3201
Broadmoor	Delachaise 3200	R/R Asph 5.5"	13.00	7.00	10.11	SY	3202
Broadmoor	Delachaise 3200	R/R Asph 5.5"	30.00	11.00	36.67	SY	3201
Broadmoor	Delachaise 3200	R/R Conc SW 4"	26.00	4.00	11.56	SY	3226
Broadmoor	Delachaise 3300	R/R Conc SW 4"	6.00	4.00	2.67	SY	3306
Broadmoor	Delachaise 3300	R/R Conc SW 4"	14.00	4.00	6.22	SY	3320
Broadmoor	Delachaise 3300	R/R Conc SW 4"	4.00	4.00	1.78	SY	3325
Broadmoor	Delachaise 3300	R/R Conc SW 4"	16.00	4.00	7.11	SY	3343
Broadmoor	Delachaise 3400	R/R Conc SW 4"	25.00	4.00	11.11	SY	3420
Broadmoor	Delachaise 3400	R/R Conc SW 4"	14.00	4.00	6.22	SY	3400
Broadmoor	Delachaise 3400	R/R Conc SW 4"	14.00	4.00	6.22	SY	3401
Broadmoor	Delachaise 3400	R/R Conc SW 4"	10.00	4.00	4.44	SY	3406
Broadmoor	Delachaise 3400	R/R Asph 5.5"	13.00	9.00	13.00	SY	3424
Broadmoor	Delachaise 3400	R/R Conc SW 4"	24.00	4.00	10.67	SY	3411
Broadmoor	Delachaise 3500	Adjust CB/MH	0.00	0.00	1.00	EA	3503
Broadmoor	Delachaise 3500	R/R Asph 5.5"	14.00	11.00	17.11	SY	3509
Broadmoor	Delachaise 3500	R/R Asph 5.5"	22.00	11.00	26.89	SY	3515
Broadmoor	Delachaise 3500	R/R Conc SW 4"	107.00	4.00	47.56	SY	3516
Broadmoor	Delachaise 3500	R/R Conc SW 4"	36.00	4.00	16.00	SY	Opposite 3529
Broadmoor	Delachaise 3500	R/R Conc SW 4"	26.00	4.00	11.56	SY	3533
Broadmoor	Delachaise 3500	R/R Conc SW 4"	18.00	4.00	8.00	SY	3541
Broadmoor	Delachaise 3600	R/R Conc SW 4"	75.00	4.00	33.33	SY	3600
Broadmoor	Delachaise 3600	R/R Conc SW 4"	15.00	4.00	6.67	SY	3601
Broadmoor	Delachaise 3600	R/R Conc SW 4"	17.00	4.00	7.56	SY	3611
Broadmoor	Delachaise 3600	R/R Conc SW 4"	21.00	4.00	9.33	SY	3621
Broadmoor	Delachaise 3600	R/R Conc SW 4"	11.00	4.00	4.89	SY	3607
Broadmoor	Delachaise 3700	R/R Conc SW 4"	14.00	4.00	6.22	SY	3735
Broadmoor	Delachaise 3700	R/R Curb	10.00	0.00	10.00	LF	Opposite 3725
Broadmoor	Delachaise 3700	R/R Conc SW 4"	8.00	4.00	3.56	SY	3716
Broadmoor	Delachaise 3700	R/R Conc SW 4"	8.00	4.00	3.56	SY	3707
Broadmoor	Delachaise 3700	R/R Conc SW 4"	21.00	4.00	9.33	SY	3703
Broadmoor	Delachaise 3800	R/R Asph 5.5"	30.00	7.00	23.33	SY	3825
Broadmoor	Delachaise 3800	R/R Conc SW 4"	41.00	4.00	18.22	SY	3835
Broadmoor	Delachaise 3800	R/R Conc SW 4"	28.00	4.00	12.44	SY	Opposite 3822

Broadmoor

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Broadmoor	Delachaise 3800	R/R Asph 5.5"	57.00	13.00	82.33	SY	3811
Broadmoor	Delachaise 3800	R/R Conc SW 4"	15.00	4.00	6.67	SY	3809
Broadmoor	Delachaise 3800	R/R Conc DW 6"	14.00	6.00	9.33	SY	3809
Broadmoor	Delachaise 3800	R/R Asph 5.5"	18.00	9.00	18.00	SY	3835
Broadmoor	Delachaise 3900	R/R Conc SW 4"	69.00	4.00	30.67	SY	3926
Broadmoor	Delachaise 3900	R/R Asph 5.5"	39.00	7.00	30.33	SY	3948
Broadmoor	Delachaise 3900	R/R Conc SW 4"	58.00	4.00	25.78	SY	Opposite 3948
Broadmoor	Delachaise 3900	R/R Asph 5.5"	21.00	8.00	18.67	SY	3948
Broadmoor	Delachaise 3900	R/R Conc SW 4"	68.00	4.00	30.32	SY	3948
Broadmoor	Delachaise 3900	R/R Conc SW 4"	21.00	4.00	9.33	SY	3942
Broadmoor	Delachaise 3900	R/R Conc SW 4"	10.00	4.00	4.44	SY	3936
Broadmoor	Delachaise 3900	R/R Conc SW 4"	6.00	4.00	2.67	SY	Opposite 3920
Broadmoor	Delachaise 3900	R/R Asph 5.5"	20.00	8.00	17.78	SY	Opposite 3916
Broadmoor	Delachaise 3900	R/R Asph 5.5"	24.00	9.00	24.00	SY	3905
Broadmoor	Delachaise 3900	R/R Asph 5.5"	38.00	9.00	38.00	SY	Opposite 3938
Broadmoor	Eden 4000	R/R Conc DW 6"	8.00	6.00	5.33	SY	4000
Broadmoor	Eden 4000	R/R Conc SW 4"	70.00	4.00	31.11	SY	4000
Broadmoor	Eden 4000	R/R Conc SW 4"	20.00	4.00	8.89	SY	4000
Broadmoor	Eden 4000	HC Ramp @ Intersection	11.00	11.00	13.44	SY	Intersection at S. Dupre
Broadmoor	Eden 4000	R/R Conc SW 4"	107.00	4.00	47.56	SY	4030
Broadmoor	Eden 4100	R/R Conc DW 6"	8.00	6.00	5.33	SY	4121
Broadmoor	Eden 4100	R/R Conc SW 4"	36.00	4.00	16.00	SY	4123
Broadmoor	Eden 4100	R/R Conc SW 4"	70.00	4.00	31.11	SY	4107 to 4109
Broadmoor	Eden 4100	R/R Conc SW 4"	20.00	4.00	8.89	SY	4121
Broadmoor	Eden 4200	R/R Conc SW 4"	12.00	4.00	5.33	SY	4205
Broadmoor	Eden 4300	R/R Conc SW 4"	8.00	3.00	2.67	SY	4328
Broadmoor	Eden 4400	R/R Conc Pvmt 8"	26.00	10.00	28.89	SY	4409
Broadmoor	Eden 4400	R/R Conc Pvmt 8"	41.00	23.25	105.92	SY	Intersection at S. Rendon (northwest to southeast corner)
Broadmoor	Eden 4400	R/R Conc Pvmt 8"	16.00	10.00	17.78	SY	4429
Broadmoor	Eden 4500	R/R Conc SW 4"	20.00	4.00	8.89	SY	4516
Broadmoor	Eden 4500	R/R Conc SW 4"	20.00	4.00	8.89	SY	4527
Broadmoor	Eden 4500	R/R Conc Pvmt 8"	60.00	13.00	86.67	SY	4527

Broadmoor

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Broadmoor	Elba 4000	R/R Curb	2.00	0.00	2.00	LF	4009
Broadmoor	Elba 4000	R/R Curb	15.00	0.00	15.00	LF	4030
Broadmoor	Elba 4000	R/R Conc Pvmt 8"	30.00	14.50	48.33	SY	Intersection at S. Dupre
Broadmoor	Elba 4000	R/R Conc SW 4"	8.00	4.00	3.56	SY	4009
Broadmoor	Elba 4000	R/R Conc SW 4"	75.00	4.00	33.33	SY	4030
Broadmoor	Elba 4000	R/R Conc Pvmt 8"	12.00	8.00	10.67	SY	4006
Broadmoor	Elba 4100	R/R Conc SW 4"	12.00	4.00	5.33	SY	4111
Broadmoor	Elba 4200	R/R Conc Pvmt 8"	6.00	6.00	4.00	SY	Intersection at S. Salcedo
Broadmoor	Elba 4200	R/R Conc Pvmt 8"	25.00	7.00	19.44	SY	4201
Broadmoor	Elba 4300	R/R Conc Pvmt 8"	15.00	26.00	43.33	SY	4306
Broadmoor	Elba 4300	R/R Conc SW 4"	12.00	4.00	5.33	SY	4306
Broadmoor	Elba 4300	R/R Conc SW 4"	8.00	4.00	3.56	SY	4300
Broadmoor	Elba 4400	R/R Conc Pvmt 8"	30.00	13.00	43.33	SY	4419
Broadmoor	Elba 4400	R/R Conc SW 4"	20.00	4.00	8.89	SY	4415
Broadmoor	Elba 4500	R/R Conc SW 4"	8.00	4.00	3.56	SY	4528
Broadmoor	Gen Pershing 4000	R/R Asph 5.5"	81.00	24.00	216.00	SY	4001
Broadmoor	Gen Pershing 4000	R/R Conc SW 4"	20.00	4.00	8.89	SY	4001
Broadmoor	Gen Pershing 4100	R/R Asph 5.5"	33.00	24.00	88.00	SY	4123
Broadmoor	Gen Pershing 4100	R/R Asph 5.5"	49.00	24.00	82.67	SY	Intersection at S. Dupre
Broadmoor	Gen Pershing 4100	R/R Asph 5.5"	111.00	24.00	296.00	SY	4100
Broadmoor	Gen Pershing 4100	R/R Asph 5.5"	25.00	12.00	33.33	SY	4125
Broadmoor	Gen Pershing 4100	R/R Conc SW 4"	12.00	4.00	5.33	SY	4133
Broadmoor	Gen Pershing 4200	R/R Asph 5.5"	30.00	5.00	16.67	SY	4215
Broadmoor	Gen Pershing 4200	R/R Asph 5.5"	20.00	10.00	2222.00	SY	4214
Broadmoor	Gen Pershing 4200	R/R Conc SW 4"	10.00	4.00	4.44	SY	4231
Broadmoor	Gen Pershing 4200	R/R Asph 5.5"	35.00	11.00	42.78	SY	4220
Broadmoor	Gen Pershing 4200	R/R Conc SW 4"	16.00	4.00	7.11	SY	4210
Broadmoor	Gen Pershing 4200	R/R Conc SW 4"	12.00	4.00	5.33	SY	4201
Broadmoor	Gen Pershing 4300	R/R Conc SW 4"	12.00	4.00	5.33	SY	4314
Broadmoor	Gen Pershing 4300	R/R Asph 5.5"	61.00	20.00	135.56	SY	4320
Broadmoor	Gen Pershing 4300	R/R Conc SW 4"	61.00	4.00	27.11	SY	4301
Broadmoor	Gen Pershing 4300	R/R Asph 5.5"	20.00	10.00	22.22	SY	4315

Broadmoor

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Broadmoor	Gen Pershing 4300	R/R Conc SW 4"	50.00	4.00	22.22	SY	4308
Broadmoor	Gen Pershing 4300	R/R Asph 5.5"	37.00	20.00	82.22	SY	4301
Broadmoor	Gen Pershing 4300	Adjust CB/MH	0.00	0.00	1.00	EA	Intersection at S. Salcedo
Broadmoor	Gen Pershing 4300	R/R Conc SW 4"	24.00	3.00	8.00	SY	4319
Broadmoor	Gen Pershing 4300	R/R Asph 5.5"	10.00	10.00	11.11	SY	Intersection at S. Salcedo
Broadmoor	Gen Pershing 4400	R/R Asph 5.5"	12.00	5.00	6.67	SY	4421
Broadmoor	Gen Pershing 4400	R/R Asph 5.5"	23.00	10.00	25.56	SY	4426
Broadmoor	Gen Pershing 4400	R/R Asph 5.5"	23.00	30.00	76.67	SY	4432
Broadmoor	Gen Pershing 4400	R/R Conc SW 4"	30.00	3.00	10.00	SY	4428
Broadmoor	Gen Pershing 4400	R/R Asph 5.5"	23.00	54.00	138.00	SY	4400
Broadmoor	Gen Pershing 4400	R/R Asph 5.5"	43.00	23.00	109.89	SY	4438
Broadmoor	Gen Pershing 4400	R/R Conc Pvmt 8"	20.00	20.00	44.44	SY	Intersection at S. Lopez
Broadmoor	Gen Pershing 4400	R/R Conc SW 4"	23.00	3.00	7.67	SY	4428
Broadmoor	Gen Pershing 4500	HC Ramp @ Intersection	8.00	8.00	7.11	SY	Intersection at S. Rendon (northeast corner)
Broadmoor	Gen Pershing 4500	R/R Asph 5.5"	43.00	33.00	157.67	SY	Intersection at S. Rendon
Broadmoor	General Pershing 3000	R/R Asph 5.5"	40.00	9.00	40.00	SY	Opposite 3015
Broadmoor	General Pershing 3000	R/R Conc SW 4"	52.00	4.00	23.11	SY	3030
Broadmoor	General Pershing 3000	R/R Conc SW 4"	210.00	4.00	93.33	SY	3018 to 3000
Broadmoor	General Pershing 3000	R/R Conc SW 4"	30.00	4.00	13.33	SY	3001
Broadmoor	General Pershing 3100	R/R Conc DW 6"	18.00	8.00	16.00	SY	Opposite 3111
Broadmoor	General Pershing 3100	R/R Conc SW 4"	36.00	4.00	16.00	SY	Opposite 3108
Broadmoor	General Pershing 3100	R/R Conc SW 4"	26.00	4.00	11.56	SY	3130
Broadmoor	General Pershing 3100	R/R Conc SW 4"	14.00	4.00	6.22	SY	3101
Broadmoor	General Pershing 3200	R/R Conc SW 4"	44.00	4.00	19.56	SY	3215
Broadmoor	General Pershing 3200	R/R Conc SW 4"	11.00	4.00	4.89	SY	3201
Broadmoor	General Pershing 3200	R/R Conc SW 4"	45.00	4.00	20.00	SY	3221
Broadmoor	General Pershing 3200	R/R Conc SW 4"	32.00	4.00	14.22	SY	3200
Broadmoor	General Pershing 3300	R/R Conc SW 4"	85.00	4.00	37.78	SY	Opposite 3330
Broadmoor	General Pershing 3300	R/R Conc SW 4"	45.00	4.00	20.00	SY	3301 to 3315
Broadmoor	General Pershing 3400	R/R Conc SW 4"	22.00	4.00	9.78	SY	3417



Broadmoor

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Broadmoor	General Pershing 3400	R/R Conc SW 4"	41.00	4.00	16.22	SY	Opposite 3417
Broadmoor	General Pershing 3400	R/R Conc SW 4"	77.00	4.00	34.22	SY	Opposite 3425
Broadmoor	General Pershing 3400	R/R Conc SW 4"	53.00	4.00	23.56	SY	3429
Broadmoor	General Pershing 3400	R/R Conc SW 4"	12.00	4.00	5.33	SY	3417
Broadmoor	General Pershing 3400	R/R Conc SW 4"	74.00	4.00	32.89	SY	3401
Broadmoor	General Pershing 3500	R/R Conc SW 4"	21.00	4.00	9.33	SY	3500
Broadmoor	General Pershing 3500	R/R Conc SW 4"	90.00	4.00	40.00	SY	3500
Broadmoor	General Pershing 3500	R/R Conc SW 4"	77.00	4.00	34.22	SY	3501
Broadmoor	General Pershing 3500	R/R Asph 5.5"	108.00	8.00	96.00	SY	3501
Broadmoor	General Pershing 3600	R/R Conc SW 4"	26.00	4.00	11.56	SY	Opposite 3617
Broadmoor	General Pershing 3600	R/R Conc SW 4"	14.00	4.00	6.22	SY	3606
Broadmoor	General Pershing 3600	R/R Conc SW 4"	21.00	4.00	9.33	SY	3624
Broadmoor	General Pershing 3700	R/R Conc SW 4"	13.00	4.00	5.78	SY	3728
Broadmoor	General Pershing 3700	R/R Asph 5.5"	9.00	4.00	4.00	SY	3728
Broadmoor	General Pershing 3700	R/R Conc SW 4"	4.00	4.00	1.78	SY	3715
Broadmoor	General Pershing 3700	R/R Conc SW 4"	17.00	4.00	7.56	SY	3714
Broadmoor	General Pershing 3700	R/R Conc SW 4"	13.00	4.00	5.78	SY	Opposite 3710
Broadmoor	General Pershing 3700	R/R Asph 5.5"	19.00	13.00	27.44	SY	Opposite 3706
Broadmoor	General Pershing 3700	R/R Asph 5.5"	29.00	13.00	41.89	SY	3710
Broadmoor	General Pershing 3800	R/R Conc SW 4"	7.00	4.00	3.11	SY	Opposite 3827
Broadmoor	General Pershing 3800	R/R Conc SW 4"	4.00	4.00	1.78	SY	3811
Broadmoor	General Pershing 3800	R/R Asph 5.5"	28.00	2.00	6.22	SY	Opposite 3827
Broadmoor	General Pershing 3800	R/R Conc SW 4"	18.00	4.00	8.00	SY	3827
Broadmoor	General Pershing 3800	R/R Conc SW 4"	8.00	4.00	3.56	SY	3825
Broadmoor	General Pershing 3800	R/R Conc SW 4"	4.00	4.00	1.78	SY	3824
Broadmoor	General Pershing 3900	R/R Asph 5.5"	10.00	9.00	10.00	SY	3911
Broadmoor	General Pershing 3900	R/R Conc SW 4"	5.00	4.00	2.22	SY	3900
Broadmoor	General Taylor 3000	R/R Conc SW 4"	46.00	4.00	20.44	SY	3023
Broadmoor	General Taylor 3000	R/R Conc SW 4"	68.00	4.00	30.22	SY	Opposite 3017
Broadmoor	General Taylor 3000	R/R Conc SW 4"	6.00	4.00	2.67	SY	3026
Broadmoor	General Taylor 3100	R/R Conc SW 4"	5.00	4.00	2.22	SY	3105
Broadmoor	General Taylor 3100	R/R Conc SW 4"	15.00	4.00	6.67	SY	3100
Broadmoor	General Taylor 3100	R/R Conc SW 4"	9.00	4.00	4.00	SY	3109
Broadmoor	General Taylor 3100	R/R Conc SW 4"	28.00	4.00	12.44	SY	3123
Broadmoor	General Taylor 3100	R/R Conc SW 4"	15.00	4.00	6.67	SY	3132

Broadmoor

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Broadmoor	General Taylor 3100	R/R Conc SW 4"	19.00	4.00	8.44	SY	3101
Broadmoor	General Taylor 3100	R/R Conc SW 4"	30.00	4.00	13.33	SY	3116
Broadmoor	General Taylor 3200	R/R Conc SW 4"	30.00	4.00	13.33	SY	3201
Broadmoor	General Taylor 3200	R/R Conc SW 4"	5.00	4.00	2.22	SY	3228
Broadmoor	General Taylor 3200	R/R Conc SW 4"	84.00	4.00	37.33	SY	3227
Broadmoor	General Taylor 3200	R/R Conc SW 4"	20.00	4.00	8.89	SY	3221
Broadmoor	General Taylor 3200	R/R Conc SW 4"	12.00	4.00	5.33	SY	3208
Broadmoor	General Taylor 3200	R/R Conc SW 4"	9.00	4.00	4.00	SY	3232
Broadmoor	General Taylor 3300	R/R Conc SW 4"	28.00	4.00	12.44	SY	Opposite 3305
Broadmoor	General Taylor 3300	R/R Conc SW 4"	15.00	4.00	6.67	SY	3301
Broadmoor	General Taylor 3300	R/R Conc SW 4"	13.00	4.00	5.78	SY	3314
Broadmoor	General Taylor 3300	R/R Conc SW 4"	5.00	4.00	2.22	SY	3313
Broadmoor	General Taylor 3300	R/R Conc SW 4"	5.00	4.00	2.22	SY	3327
Broadmoor	General Taylor 3300	R/R Conc SW 4"	20.00	4.00	8.89	SY	3327
Broadmoor	General Taylor 3400	R/R Conc SW 4"	35.00	4.00	15.56	SY	3419
Broadmoor	General Taylor 3400	R/R Conc SW 4"	59.00	4.00	26.22	SY	3420
Broadmoor	General Taylor 3400	R/R Conc SW 4"	25.00	4.00	11.11	SY	Opposite 3419
Broadmoor	General Taylor 3400	R/R Asph 5.5"	36.00	13.00	52.00	SY	3419
Broadmoor	General Taylor 3400	R/R Conc SW 4"	4.00	4.00	1.78	SY	3415
Broadmoor	General Taylor 3400	R/R Conc SW 4"	27.00	4.00	12.00	SY	Opposite 3405
Broadmoor	General Taylor 3400	R/R Conc SW 4"	13.00	4.00	5.78	SY	3405
Broadmoor	General Taylor 3500	R/R Conc SW 4"	90.00	4.00	40.00	SY	Opposite 3523
Broadmoor	General Taylor 3500	R/R Conc SW 4"	40.00	4.00	17.78	SY	3500
Broadmoor	General Taylor 3500	R/R Conc SW 4"	25.00	4.00	11.11	SY	3501
Broadmoor	General Taylor 3600	R/R Conc SW 4"	12.00	4.00	5.33	SY	3600
Broadmoor	General Taylor 3600	R/R Conc SW 4"	48.00	4.00	21.33	SY	3601
Broadmoor	General Taylor 3600	R/R Conc SW 4"	29.00	4.00	12.89	SY	3611
Broadmoor	General Taylor 3600	R/R Conc SW 4"	62.00	4.00	27.56	SY	Opposite 3617
Broadmoor	General Taylor 3700	R/R Conc SW 4"	22.00	4.00	9.78	SY	3721
Broadmoor	General Taylor 3700	R/R Conc SW 4"	30.00	4.00	13.33	SY	3727
Broadmoor	General Taylor 3700	R/R Conc SW 4"	42.00	4.00	18.67	SY	3701
Broadmoor	General Taylor 3800	R/R Conc SW 4"	34.00	4.00	15.11	SY	3820
Broadmoor	General Taylor 3800	R/R Conc SW 4"	30.00	4.00	13.33	SY	3830
Broadmoor	General Taylor 3800	R/R Conc SW 4"	12.00	4.00	5.33	SY	3829
Broadmoor	General Taylor 3800	R/R Conc SW 4"	18.00	4.00	8.00	SY	3812



Broadmoor

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Broadmoor	General Taylor 3800	R/R Conc SW 4"	31.00	4.00	13.78	SY	3815
Broadmoor	General Taylor 3800	R/R Conc SW 4"	23.00	4.00	10.22	SY	3827
Broadmoor	General Taylor 3800	R/R Conc SW 4"	46.00	4.00	20.44	SY	3809
Broadmoor	General Taylor 3900	R/R Conc SW 4"	14.00	4.00	6.22	SY	3943
Broadmoor	General Taylor 3900	R/R Conc SW 4"	8.00	4.00	3.56	SY	3907
Broadmoor	General Taylor 3900	R/R Conc SW 4"	8.00	4.00	3.56	SY	3919
Broadmoor	General Taylor 3900	R/R Conc SW 4"	18.00	4.00	8.00	SY	3930
Broadmoor	General Taylor 3900	R/R Conc SW 4"	99.00	4.00	44.00	SY	Opposite 3943
Broadmoor	General Taylor 3900	R/R Asph 5.5"	17.00	16.00	30.22	SY	3945
Broadmoor	General Taylor 3900	R/R Conc SW 4"	4.00	4.00	1.78	SY	3925
Broadmoor	Jena 3000	R/R Conc Pvmt 8"	31.00	13.00	44.78	SY	3000
Broadmoor	Jena 3000	R/R Conc Pvmt 8"	31.00	8.00	27.56	SY	3000
Broadmoor	Jena 3000	R/R Conc Pvmt 8"	62.00	26.00	179.11	SY	3027
Broadmoor	Jena 3100	R/R Conc SW 4"	4.00	4.00	1.78	SY	Intersection of Jena and S. Derbigny (Northeast Quad)
Broadmoor	Jena 3100	R/R Conc DW 6"	38.00	2.00	8.44	SY	3118
Broadmoor	Jena 3100	R/R Conc SW 4"	29.00	4.00	12.89	SY	3118
Broadmoor	Jena 3200	R/R Conc Pvmt 8"	55.00	13.00	79.44	SY	3218
Broadmoor	Jena 3200	R/R Conc SW 4"	12.00	4.00	5.33	SY	Opposite 3231
Broadmoor	Jena 3200	R/R Conc SW 4"	14.00	4.00	6.22	SY	Opposite 3202
Broadmoor	Jena 3200	R/R Conc Pvmt 8"	20.00	13.00	28.89	SY	3225
Broadmoor	Jena 3200	R/R Conc SW 4"	5.00	4.00	2.22	SY	Opposite 3210
Broadmoor	Jena 3300	R/R Conc SW 4"	4.00	4.00	1.78	SY	3350
Broadmoor	Jena 3300	R/R Conc Pvmt 8"	48.00	13.00	69.33	SY	3320
Broadmoor	Jena 3300	R/R Conc SW 4"	31.00	4.00	13.78	SY	3310
Broadmoor	Jena 3400	R/R Conc SW 4"	46.00	4.00	20.44	SY	3499
Broadmoor	Jena 3400	R/R Conc Pvmt 8"	51.00	47.50	269.17	SY	Intersection of S. Johnson
Broadmoor	Jena 3400	R/R Conc SW 4"	10.00	3.00	3.33	SY	3450
Broadmoor	Jena 3400	R/R Asph 5.5"	68.00	9.00	68.00	SY	3451
Broadmoor	Jena 3500	R/R Asph 5.5"	15.00	7.00	11.67	SY	3500
Broadmoor	Jena 3500	R/R Asph 5.5"	7.00	6.00	4.67	SY	3500
Broadmoor	Jena 3500	R/R Asph 5.5"	18.00	8.00	16.00	SY	3504
Broadmoor	Jena 3500	R/R Asph 5.5"	10.00	4.00	4.44	SY	3510
Broadmoor	Jena 3500	R/R Asph 5.5"	84.00	18.00	168.00	SY	3510

Broadmoor

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Broadmoor	Jena 3500	R/R Asph 5.5"	10.00	26.00	28.89	SY	Intersection of S. Galvez (Eastbound at south leg)
Broadmoor	Jena 3600	R/R Asph 5.5"	21.00	27.00	63.00	SY	Intersection of Jena at S. Miro (Southwest Quad)
Broadmoor	Jena 3600	R/R Conc SW 4"	5.00	4.00	2.22	SY	3614
Broadmoor	Jena 3600	R/R Conc SW 4"	14.00	4.00	6.22	SY	3636
Broadmoor	Jena 3700	R/R Asph 5.5"	25.00	20.75	57.64	SY	Intersection of Jena at S. Tonti (Southwest Quad)
Broadmoor	Jena 3700	R/R Curb	12.00	0.00	12.00	LF	3700
Broadmoor	Jena 3700	R/R Conc SW 4"	9.00	4.00	4.00	SY	Opposite 3720
Broadmoor	Jena 3700	R/R Conc SW 4"	22.00	4.00	9.78	SY	Opposite 3714
Broadmoor	Jena 3700	R/R Conc SW 4"	25.00	4.00	11.11	SY	3700
Broadmoor	Jena 3700	R/R Asph 5.5"	12.00	2.00	2.67	SY	3700
Broadmoor	Jena 3800	R/R Conc SW 4"	29.00	4.00	12.89	SY	3800
Broadmoor	Jena 3800	R/R Conc SW 4"	13.00	4.00	5.78	SY	3838
Broadmoor	Jena 3800	R/R Conc SW 4"	22.00	4.00	9.78	SY	3837
Broadmoor	Jena 3900	R/R Asph 5.5"	4.00	10.00	4.44	SY	3910
Broadmoor	Jena 3900	R/R Conc SW 4"	15.00	4.00	6.67	SY	3912
Broadmoor	Jena 4200	R/R Conc Pvmt 8"	50.00	13.00	72.22	SY	4236
Broadmoor	Jena 4300	R/R Asph 5.5"	42.00	26.00	121.33	SY	4325
Broadmoor	Jena 4300	R/R Asph 5.5"	132.00	13.00	190.67	SY	4317 to 4303
Broadmoor	Jena 4300	R/R Asph 5.5"	20.00	13.00	28.89	SY	4300
Broadmoor	Jena 4400	R/R Asph 5.5"	195.00	18.00	390.00	SY	4400
Broadmoor	Jena 4400	R/R Asph 5.5"	42.00	29.75	138.83	SY	Intersection at S. Lopez
Broadmoor	Milan 3000	R/R Conc SW 4"	48.00	4.00	21.83	SY	3001
Broadmoor	Milan 3000	R/R Asph 5.5"	10.00	13.00	14.44	SY	Opposite 3022
Broadmoor	Milan 3000	R/R Conc SW 4"	18.00	4.00	8.00	SY	Opposite 3035
Broadmoor	Milan 3000	R/R Asph 5.5"	29.00	8.00	25.78	SY	Opposite 3035
Broadmoor	Milan 3000	R/R Asph 5.5"	14.00	13.00	20.22	SY	3029
Broadmoor	Milan 3100	R/R Conc SW 4"	26.00	4.00	11.56	SY	3105
Broadmoor	Milan 3100	R/R Conc SW 4"	23.00	4.00	10.22	SY	3109
Broadmoor	Milan 3100	R/R Asph 5.5"	23.00	12.00	30.67	SY	3103
Broadmoor	Milan 3100	R/R Conc SW 4"	41.00	4.00	18.22	SY	Opposite 3133
Broadmoor	Milan 3200	R/R Conc SW 4"	9.00	4.00	4.00	SY	3214

Broadmoor

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Broadmoor	Milan 3200	R/R Conc SW 4"	5.00	4.00	2.22	SY	3203
Broadmoor	Milan 3200	R/R Conc SW 4"	14.00	4.00	6.22	SY	3225
Broadmoor	Milan 3200	R/R Asph 5.5"	10.00	6.00	6.67	SY	3200
Broadmoor	Milan 3300	R/R Asph 5.5"	10.00	12.00	13.33	SY	3322
Broadmoor	Milan 3300	R/R Conc SW 4"	46.00	4.00	20.44	SY	3301
Broadmoor	Milan 3300	R/R Conc SW 4"	10.00	4.00	4.44	SY	3324
Broadmoor	Milan 3300	R/R Conc SW 4"	72.00	4.00	32.89	SY	3325
Broadmoor	Milan 3300	R/R Conc SW 4"	36.00	4.00	16.00	SY	3330
Broadmoor	Milan 3400	R/R Conc SW 4"	40.00	4.00	17.78	SY	3431
Broadmoor	Milan 3400	R/R Conc SW 4"	15.00	4.00	6.67	SY	3401
Broadmoor	Milan 3400	R/R Conc SW 4"	13.00	4.00	5.78	SY	3407
Broadmoor	Milan 3400	R/R Conc SW 4"	78.00	4.00	34.67	SY	3426
Broadmoor	Milan 3500	R/R Asph 5.5"	27.00	4.00	12.00	SY	35000
Broadmoor	Milan 3500	R/R Conc SW 4"	78.00	4.00	34.67	SY	3500
Broadmoor	Milan 3500	R/R Conc SW 4"	83.00	4.00	36.89	SY	3524 to 3530
Broadmoor	Milan 3500	R/R Conc SW 4"	74.00	4.00	32.89	SY	3501
Broadmoor	Milan 3700	R/R Conc SW 4"	24.00	4.00	10.67	SY	3702
Broadmoor	Milan 3700	R/R Asph 5.5"	96.00	13.00	138.67	SY	3704
Broadmoor	Milan 3700	R/R Asph 5.5"	100.00	17.00	188.89	SY	3726
Broadmoor	Milan 3700	R/R Conc SW 4"	23.00	4.00	10.22	SY	3714
Broadmoor	Milan 3700	R/R Conc SW 4"	27.00	4.00	12.00	SY	3716
Broadmoor	Milan 3700	R/R Conc SW 4"	29.00	4.00	12.89	SY	3730
Broadmoor	Milan 3700	R/R Conc SW 4"	17.00	4.00	7.56	SY	3726
Broadmoor	Robert 2900	R/R Conc SW 4"	25.00	3.00	8.33	SY	2910
Broadmoor	Robert 2900	R/R Asph 5.5"	35.00	8.00	31.11	SY	2900
Broadmoor	Robert 2900	R/R Asph 5.5"	12.00	7.00	9.33	SY	Intersection at S. Derbigny
Broadmoor	Robert 3000	R/R Asph 5.5"	35.00	4.00	15.56	SY	3009
Broadmoor	Robert 3000	R/R Asph 5.5"	10.00	7.00	7.78	SY	3039
Broadmoor	Robert 3000	R/R Conc SW 4"	8.00	3.00	2.67	SY	3009
Broadmoor	Robert 3000	R/R Conc SW 4"	8.00	4.00	2.67	SY	3009
Broadmoor	Robert 3000	R/R Asph 5.5"	15.00	4.00	6.67	SY	Intersection at S. Prieur
Broadmoor	Robert 3100	R/R Conc SW 4"	31.00	3.00	10.33	SY	Opposite 3120
Broadmoor	Robert 3100	R/R Conc SW 4"	51.00	3.00	17.00	SY	Opposite 3138

Broadmoor

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Broadmoor	Robert 3300	R/R Asph 5.5"	20.00	4.00	8.89	SY	3300
Broadmoor	Robert 3300	R/R Conc SW 4"	30.00	3.00	10.00	SY	Opposite 3314
Broadmoor	Robert 3300	R/R Conc SW 4"	20.00	3.00	6.67	SY	3310
Broadmoor	Robert 3300	R/R Asph 5.5"	210.00	26.00	606.67	SY	3328 to 3306
Broadmoor	Robert 3300	R/R Asph 5.5"	30.00	10.00	33.33	SY	3306
Broadmoor	Robert 3400	R/R Asph 5.5"	15.00	15.00	25.00	SY	Intersection at S. Galvez (Eastside)
Broadmoor	Robert 3400	R/R Asph 5.5"	101.00	26.00	291.78	SY	3421
Broadmoor	Robert 3400	R/R Asph 5.5"	10.00	10.00	11.11	SY	3430
Broadmoor	Robert 3400	R/R Conc SW 4"	18.00	3.00	6.00	SY	3421
Broadmoor	Robert 3400	R/R Curb	3.00	0.00	3.00	LF	Intersection at S. Galvez (Eastside)
Broadmoor	Robert 3500	Adjust CB/MH	0.00	0.00	1.00	EA	3541
Broadmoor	Robert 3500	R/R Asph 5.5"	38.00	26.00	109.78	SY	3500
Broadmoor	Robert 3500	R/R Asph 5.5"	45.00	40.00	200.00	SY	3508
Broadmoor	Robert 3500	R/R Asph 5.5"	30.00	9.00	30.00	SY	3500
Broadmoor	Robert 3500	R/R Conc SW 4"	36.00	3.00	12.00	SY	Opposite 3541
Broadmoor	Robert 3500	R/R Asph 5.5"	14.00	8.00	12.44	SY	3541
Broadmoor	Robert 3500	R/R Asph 5.5"	20.00	9.00	20.00	SY	3534
Broadmoor	Robert 3500	R/R Asph 5.5"	50.00	20.00	111.11	SY	Intersection at S. Tonti (West side)
Broadmoor	Robert 3600	R/R Asph 5.5"	184.00	26.00	531.56	SY	3621
Broadmoor	Robert 3600	R/R Conc SW 4"	14.00	3.00	4.67	SY	Opposite 3621
Broadmoor	Robert 3600	R/R Asph 5.5"	48.00	35.50	189.33	SY	Intersection at S. Tonti (East side)
Broadmoor	Robert 3700	R/R Asph 5.5"	70.00	26.00	202.22	SY	3700
Broadmoor	Robert 3700	R/R Asph 5.5"	44.00	34.00	166.22	SY	Intersection at S. Rocheblave (West side)
Broadmoor	Robert 3700	R/R Asph 5.5"	92.00	26.00	265.78	SY	3720
Broadmoor	Robert 3700	R/R Asph 5.5"	30.00	10.00	33.33	SY	Intersection at S. Rocheblave (East side)
Broadmoor	S Dorgenois 3300	R/R Asph 5.5"	56.00	12.00	74.67	SY	3301
Broadmoor	S Dorgenois 3300	R/R Conc SW 4"	30.00	3.00	10.00	SY	3311
Broadmoor	S Dorgenois 3400	R/R Conc SW 4"	12.00	3.00	4.00	SY	3401
Broadmoor	S Dorgenois 3700	R/R Asph 5.5"	40.00	12.00	53.33	SY	3701
Broadmoor	S Dorgenois 3700	R/R Conc SW 4"	80.00	4.00	35.56	SY	3730
Broadmoor	S Dorgenois 4200	R/R Conc SW 4"	100.00	5.00	55.56	SY	4220
Broadmoor	S Dorgenois 4200	R/R Asph 5.5"	25.00	48.00	109.33	SY	Intersection at General Taylor

Broadmoor

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Broadmoor	S Dorgenois 4200	R/R Asph 5.5"	30.00	8.00	26.67	SY	4201
Broadmoor	S Dorgenois 4200	R/R Conc SW 4"	15.00	5.00	8.33	SY	4201
Broadmoor	S Dorgenois 4200	R/R Conc SW 4"	10.00	5.00	5.56	SY	4202
Broadmoor	S Dorgenois 4200	R/R Conc SW 4"	45.00	5.00	25.00	SY	4218
Broadmoor	S Dorgenois 4300	R/R Conc SW 4"	42.00	5.00	23.33	SY	4300
Broadmoor	S Dorgenois 4300	R/R Conc SW 4"	16.00	5.00	8.89	SY	4308
Broadmoor	S Dorgenois 4300	R/R Asph 5.5"	6.00	6.00	4.00	SY	Intersection at General Pershing
Broadmoor	S Dupre 1700	R/R Asph 5.5"	97.00	25.00	269.44	SY	1812
Broadmoor	S Dupre 1700	R/R Asph 5.5"	10.00	10.00	11.11	SY	1718
Broadmoor	S Dupre 1700	Adjust CB/MH	0.00	0.00	1.00	EA	1718
Broadmoor	S Dupre 1700	R/R Asph 5.5"	10.00	10.00	11.11	SY	1718
Broadmoor	S Dupre 1700	R/R Conc SW 4"	50.00	4.00	22.22	SY	1718
Broadmoor	S Dupre 1700	R/R Asph 5.5"	75.00	25.00	208.33	SY	1740
Broadmoor	S Dupre 1700	R/R Conc SW 4"	75.00	4.00	33.33	SY	1740
Broadmoor	S Dupre 1800	R/R Curb	3.00	0.00	3.00	LF	1830
Broadmoor	S Dupre 1800	R/R Conc SW 4"	46.00	4.00	20.44	SY	1812
Broadmoor	S Dupre 1800	R/R Conc SW 4"	9.00	4.00	4.00	SY	1811
Broadmoor	S Dupre 1800	R/R Asph 5.5"	268.00	24.00	714.67	SY	1828 to 1802
Broadmoor	S Dupre 1800	R/R Conc SW 4"	30.00	4.00	13.33	SY	1830
Broadmoor	S Dupre 1900	R/R Conc SW 4"	41.00	4.00	18.22	SY	1931
Broadmoor	S Dupre 1900	R/R Conc SW 4"	24.00	4.00	10.67	SY	1915
Broadmoor	S Dupre 1900	R/R Conc SW 4"	60.00	5.00	33.33	SY	1915
Broadmoor	S Dupre 1900	R/R Asph 5.5"	116.00	24.00	309.33	SY	1925
Broadmoor	S Dupre 1900	R/R Conc SW 4"	28.00	5.00	15.56	SY	1909
Broadmoor	S Dupre 2000	R/R Asph 5.5"	94.00	26.00	271.56	SY	2021
Broadmoor	S Galvez 4400	R/R Asph 5.5"	48.00	6.00	32.00	SY	4429
Broadmoor	S Galvez 4400	R/R Conc SW 4"	10.00	5.00	5.56	SY	4439
Broadmoor	S Galvez 4400	R/R Asph 5.5"	33.00	9.00	33.00	SY	4401
Broadmoor	S Galvez 4400	R/R Asph 5.5"	58.00	7.00	45.11	SY	4400
Broadmoor	S Galvez 4400	R/R Conc SW 4"	5.00	5.00	2.78	SY	4429
Broadmoor	S Galvez 4400	R/R Conc SW 4"	41.00	5.00	22.78	SY	4401
Broadmoor	S Galvez 4500	R/R Conc SW 4"	5.00	5.00	2.78	SY	4546
Broadmoor	S Galvez 4500	R/R Conc SW 4"	16.00	5.00	8.89	SY	4550
Broadmoor	S Galvez 4500	R/R Conc SW 4"	37.00	5.00	20.56	SY	4535

Broadmoor

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Broadmoor	S Galvez 4500	R/R Asph 5.5"	67.00	5.00	37.22	SY	4535
Broadmoor	S Galvez 4500	R/R Conc SW 4"	3.00	5.00	1.67	SY	4519
Broadmoor	S Galvez 4500	R/R Asph 5.5"	130.00	8.00	115.56	SY	4503 to 4525
Broadmoor	S Galvez 4500	R/R Asph 5.5"	110.00	5.00	61.11	SY	4516 to 4500
Broadmoor	S Galvez 4600	R/R Asph 5.5"	70.00	7.00	54.44	SY	4601
Broadmoor	S Galvez 4600	R/R Conc SW 4"	4.00	5.00	2.22	SY	4609
Broadmoor	S Galvez 4600	R/R Asph 5.5"	46.00	4.00	20.44	SY	4600
Broadmoor	S Galvez 4600	R/R Conc SW 4"	5.00	5.00	2.78	SY	4612
Broadmoor	S Galvez 4900	R/R Asph 5.5"	299.00	21.00	697.67	SY	4900 to 4934
Broadmoor	S Galvez 4900	R/R Curb	15.00	0.00	15.00	LF	4900
Broadmoor	S Galvez 4900	R/R Conc SW 4"	15.00	3.00	5.00	SY	4900
Broadmoor	S Galvez 5000	R/R Asph 5.5"	197.00	24.00	525.33	SY	5000 to 5050
Broadmoor	S Galvez 5000	R/R Conc SW 4"	26.00	4.00	11.56	SY	5001
Broadmoor	S Galvez 5000	R/R Conc SW 4"	18.00	4.00	8.00	SY	5000
Broadmoor	S Galvez 5000	R/R Curb	100.00	0.00	100.00	LF	5000
Broadmoor	S Gayoso 2100	R/R Asph 5.5"	42.00	16.00	74.67	SY	2111
Broadmoor	S Gayoso 2100	R/R Conc SW 4"	20.00	4.00	8.89	SY	2131
Broadmoor	S Gayoso 2200	R/R Asph 5.5"	325.00	18.00	650.00	SY	2210 to 2235
Broadmoor	S Gayoso 2200	R/R Conc SW 4"	28.00	4.00	12.44	SY	2231
Broadmoor	S Johnson 3700	R/R Conc SW 4"	75.00	4.00	33.33	SY	3701
Broadmoor	S Johnson 3700	R/R Conc SW 4"	28.00	4.00	12.44	SY	3720
Broadmoor	S Johnson 3700	R/R Conc SW 4"	112.00	4.00	49.78	SY	3721
Broadmoor	S Johnson 4100	R/R Curb	5.00	0.00	5.00	LF	4100
Broadmoor	S Johnson 4100	R/R Conc SW 4"	30.00	4.00	13.33	SY	4118
Broadmoor	S Johnson 4100	R/R Conc SW 4"	50.00	4.00	22.22	SY	4125
Broadmoor	S Johnson 4100	R/R Conc SW 4"	34.00	4.00	15.11	SY	4124
Broadmoor	S Johnson 4200	R/R Conc SW 4"	12.00	4.00	5.33	SY	4230
Broadmoor	S Johnson 4200	R/R Conc SW 4"	12.00	4.00	5.33	SY	4204
Broadmoor	S Johnson 4200	R/R Conc SW 4"	30.00	4.00	13.33	SY	4231
Broadmoor	S Johnson 4200	R/R Conc SW 4"	27.00	4.00	12.00	SY	4225
Broadmoor	S Johnson 4200	R/R Conc SW 4"	30.00	4.00	13.33	SY	4216
Broadmoor	S Johnson 4200	R/R Conc SW 4"	36.00	4.00	16.00	SY	4200
Broadmoor	S Johnson 4200	R/R Asph 5.5"	2.00	2.00	0.44	SY	4231
Broadmoor	S Johnson 4300	R/R Conc SW 4"	8.00	4.00	3.56	SY	4315
Broadmoor	S Johnson 4300	R/R Conc SW 4"	30.00	4.00	13.33	SY	4317



Broadmoor

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Broadmoor	S Johnson 4300	R/R Conc SW 4"	30.00	4.00	13.33	SY	4314
Broadmoor	S Johnson 4400	R/R Conc Pvmt 8"	104.00	26.00	300.44	SY	4422
Broadmoor	S Johnson 4400	R/R Conc SW 4"	75.00	4.00	33.33	SY	4401
Broadmoor	S Johnson 4400	R/R Conc Pvmt 8"	30.00	13.00	43.33	SY	4438
Broadmoor	S Johnson 4500	R/R Conc Pvmt 8"	113.00	26.00	326.44	SY	4516 to 4536
Broadmoor	S Johnson 4500	R/R Conc SW 4"	15.00	5.00	8.33	SY	4535
Broadmoor	S Johnson 4600	R/R Conc SW 4"	20.00	4.00	8.89	SY	4600
Broadmoor	S Johnson 4600	R/R Conc Pvmt 8"	145.00	26.00	418.89	SY	4600 to 4622
Broadmoor	S Johnson 4900	R/R Curb	291.00	0.00	291.00	LF	Odd side
Broadmoor	S Johnson 4900	R/R Curb	291.00	0.00	291.00	LF	Even side
Broadmoor	S Johnson 4900	R/R Conc SW 4"	12.00	4.00	5.33	SY	4930
Broadmoor	S Johnson 4900	R/R Conc SW 4"	24.00	4.00	10.67	SY	4923
Broadmoor	S Johnson 4900	R/R Asph 5.5"	291.00	26.00	840.67	SY	4900 to 4930
Broadmoor	S Johnson 4900	R/R Conc SW 4"	4.00	4.00	1.78	SY	4933
Broadmoor	S Johnson 5000	R/R Curb	271.00	0.00	271.00	LF	Even side
Broadmoor	S Johnson 5000	R/R Asph 5.5"	277.00	26.00	800.22	SY	5000 to 5030
Broadmoor	S Johnson 5000	R/R Conc SW 4"	16.00	4.00	7.11	SY	5000
Broadmoor	S Johnson 5000	R/R Curb	271.00	0.00	271.00	LF	Odd side
Broadmoor	S Lopez 1600	R/R Conc Pvmt 8"	31.00	13.00	44.78	SY	1624
Broadmoor	S Lopez 1700	R/R Conc Pvmt 8"	54.00	13.00	78.00	SY	1777
Broadmoor	S Lopez 1800	R/R Conc SW 4"	20.00	4.00	8.89	SY	1830
Broadmoor	S Lopez 1800	R/R Conc SW 4"	16.00	4.00	7.11	SY	1831
Broadmoor	S Lopez 1900	R/R Conc SW 4"	8.00	4.00	3.56	SY	1932
Broadmoor	S Lopez 1900	R/R Conc SW 4"	28.00	4.00	12.44	SY	1901
Broadmoor	S Lopez 2000	R/R Conc Pvmt 8"	85.00	8.00	75.56	SY	2031
Broadmoor	S Lopez 2100	R/R Asph 5.5"	300.00	18.00	600.00	SY	2100 to 2137
Broadmoor	S Lopez 2100	R/R Conc SW 4"	12.00	4.00	5.33	SY	2118
Broadmoor	S Lopez 2200	R/R Asph 5.5"	26.00	15.00	43.33	SY	2200 Block between McKenna & Cadiz
Broadmoor	S Lopez 2200	R/R Conc SW 4"	8.00	4.00	3.56	SY	2231
Broadmoor	S Lopez 2200	R/R Asph 5.5"	225.00	20.00	500.00	SY	2200 to 2230
Broadmoor	S Miro 3500	R/R Conc SW 4"	30.00	4.00	13.33	SY	3512
Broadmoor	S Miro 3500	R/R Conc SW 4"	40.00	4.00	17.78	SY	3501
Broadmoor	S Miro 3500	R/R Conc SW 4"	15.00	4.00	6.67	SY	3523

Broadmoor

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Broadmoor	S Miro 3500	R/R Conc DW 6"	12.00	9.00	12.00	SY	3515
Broadmoor	S Miro 3500	R/R Asph 5.5"	38.00	47.00	198.44	SY	Intersection at Delachaise
Broadmoor	S Miro 4100	R/R Asph 5.5"	20.00	6.00	13.33	SY	4106
Broadmoor	S Miro 4100	R/R Conc SW 4"	25.00	4.00	11.11	SY	4102
Broadmoor	S Miro 4100	R/R Asph 5.5"	40.00	24.00	106.67	SY	4101
Broadmoor	S Miro 4100	R/R Asph 5.5"	45.00	45.00	180.00	SY	Intersection at General Taylor
Broadmoor	S Miro 4200	R/R Asph 5.5"	12.00	12.00	16.00	SY	4200
Broadmoor	S Miro 4200	R/R Conc SW 4"	10.00	3.00	3.33	SY	4228
Broadmoor	S Miro 4200	R/R Asph 5.5"	3.00	3.00	1.00	SY	Opposite 4202
Broadmoor	S Miro 4300	R/R Conc SW 4"	4.00	4.00	1.78	SY	4310
Broadmoor	S Miro 4300	R/R Conc SW 4"	4.00	4.00	1.78	SY	4317
Broadmoor	S Prieur 3700	R/R Asph 5.5"	6.00	6.00	4.00	SY	Intersection at Delachaise
Broadmoor	S Prieur 3700	R/R Conc SW 4"	60.00	4.00	26.67	SY	3733
Broadmoor	S Prieur 3700	R/R Conc SW 4"	20.00	4.00	8.89	SY	3723
Broadmoor	S Prieur 3700	R/R Conc SW 4"	40.00	4.00	17.78	SY	3700
Broadmoor	S Prieur 4100	R/R Conc SW 4"	70.00	4.00	31.11	SY	4124
Broadmoor	S Prieur 4100	R/R Conc SW 4"	30.00	4.00	13.33	SY	4123
Broadmoor	S Prieur 4100	R/R Conc SW 4"	44.00	4.00	19.56	SY	4115
Broadmoor	S Prieur 4100	R/R Conc SW 4"	12.00	4.00	5.33	SY	4109
Broadmoor	S Prieur 4200	R/R Conc SW 4"	30.00	4.00	13.33	SY	4205
Broadmoor	S Prieur 4200	R/R Asph 5.5"	24.00	24.00	64.00	SY	4205
Broadmoor	S Prieur 4200	R/R Conc SW 4"	12.00	4.00	5.33	SY	4220
Broadmoor	S Prieur 4300	R/R Conc SW 4"	12.00	4.00	5.33	SY	4301
Broadmoor	S Prieur 4300	R/R Conc Pvmt 8"	43.00	27.00	129.00	SY	Intersection at General Pershing
Broadmoor	S Prieur 4300	R/R Conc SW 4"	30.00	4.00	13.33	SY	4300
Broadmoor	S Prieur 4300	R/R Asph 5.5"	22.00	3.00	7.33	SY	4301
Broadmoor	S Prieur 4300	R/R Asph 5.5"	100.00	24.00	266.67	SY	4335
Broadmoor	S Prieur 4300	R/R Conc SW 4"	24.00	4.00	10.67	SY	4311
Broadmoor	S Prieur 4300	R/R Conc SW 4"	26.00	4.00	11.56	SY	4336
Broadmoor	S Prieur 4300	R/R Asph 5.5"	8.00	6.00	5.33	SY	4333
Broadmoor	S Prieur 4300	R/R Asph 5.5"	24.00	10.00	26.67	SY	4311

Broadmoor

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Broadmoor	S Rendon 1600	R/R Asph 5.5"	182.00	26.00	525.78	SY	1603
Broadmoor	S Rendon 1600	R/R Conc SW 4"	31.00	4.00	13.78	SY	1635
Broadmoor	S Rendon 1700	R/R Asph 5.5"	80.00	26.00	231.11	SY	1701
Broadmoor	S Rendon 1700	R/R Conc SW 4"	10.00	5.00	5.56	SY	1719
Broadmoor	S Rendon 1700	R/R Conc SW 4"	10.00	5.00	5.56	SY	1723
Broadmoor	S Rendon 1700	R/R Conc SW 4"	30.00	5.00	16.67	SY	1727
Broadmoor	S Rendon 1800	R/R Asph 5.5"	64.00	26.00	184.89	SY	1817
Broadmoor	S Rendon 1800	R/R Asph 5.5"	134.00	26.00	387.11	SY	1823 to 1831
Broadmoor	S Rendon 1800	R/R Conc SW 4"	33.00	5.00	18.33	SY	1803
Broadmoor	S Rendon 1800	R/R Conc SW 4"	140.00	5.00	77.78	SY	1831
Broadmoor	S Rendon 1900	R/R Asph 5.5"	94.00	26.00	271.56	SY	1921
Broadmoor	S Rendon 1900	R/R Conc SW 4"	39.00	5.00	21.67	SY	1930
Broadmoor	S Rendon 1900	R/R Conc SW 4"	12.00	4.00	5.33	SY	1900
Broadmoor	S Rendon 1900	R/R Conc SW 4"	30.00	5.00	16.67	SY	1933
Broadmoor	S Rendon 2000	R/R Conc SW 4"	24.00	5.00	13.33	SY	2015
Broadmoor	S Rendon 2000	R/R Asph 5.5"	78.00	12.00	104.00	SY	2014 to 2018
Broadmoor	S Rendon 2000	R/R Conc SW 4"	25.00	5.00	13.89	SY	2030
Broadmoor	S Rendon 2000	R/R Conc SW 4"	47.00	5.00	26.11	SY	2000
Broadmoor	S Rocheblave 3700	R/R Conc SW 4"	24.00	4.00	10.67	SY	3716
Broadmoor	S Rocheblave 4200	R/R Conc SW 4"	100.00	4.00	44.44	SY	4225
Broadmoor	S Rocheblave 4200	R/R Conc SW 4"	34.00	4.00	15.11	SY	4202
Broadmoor	S Rocheblave 4200	R/R Asph 5.5"	20.00	20.00	44.44	SY	Intersection at Milan to General Taylor
Broadmoor	S Rocheblave 4300	R/R Conc SW 4"	26.00	4.00	11.56	SY	4330
Broadmoor	S Rocheblave 4300	R/R Asph 5.5"	6.00	7.00	4.67	SY	4320
Broadmoor	S Rocheblave 4300	R/R Asph 5.5"	20.00	20.00	44.44	SY	Intersection at General Pershing
Broadmoor	S Rocheblave 4400	R/R Conc SW 4"	8.00	4.00	3.56	SY	4400
Broadmoor	S Rocheblave 4500	R/R Conc SW 4"	10.00	6.00	6.67	SY	4540
Broadmoor	S Rocheblave 4900	R/R Conc SW 4"	34.00	4.00	15.11	SY	4910
Broadmoor	S Salcedo 1600	R/R Conc SW 4"	9.00	4.00	4.00	SY	1613
Broadmoor	S Salcedo 1600	R/R Conc SW 4"	9.00	4.00	4.00	SY	1601
Broadmoor	S Salcedo 1600	Adjust CB/MH	0.00	0.00	1.00	EA	1613
Broadmoor	S Salcedo 1700	R/R Conc SW 4"	12.00	4.00	5.33	SY	1731
Broadmoor	S Salcedo 1700	R/R Conc SW 4"	4.00	4.00	1.78	SY	1704

Broadmoor

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Broadmoor	S Salcedo 1800	R/R Conc SW 4"	42.00	4.00	18.67	SY	1818
Broadmoor	S Salcedo 1800	R/R Asph 5.5"	117.00	18.00	234.00	SY	1820 to 1818
Broadmoor	S Salcedo 1800	R/R Asph 5.5"	30.00	18.00	60.00	SY	1830
Broadmoor	S Salcedo 1800	R/R Asph 5.5"	49.00	18.00	98.00	SY	1811
Broadmoor	S Salcedo 1900	R/R Conc SW 4"	15.00	4.00	6.67	SY	1900
Broadmoor	S Salcedo 1900	R/R Asph 5.5"	130.00	17.00	245.56	SY	1930 to 1922
Broadmoor	S Salcedo 1900	R/R Conc SW 4"	9.00	4.00	4.00	SY	1920
Broadmoor	S Salcedo 1900	R/R Asph 5.5"	31.00	17.00	58.56	SY	1900
Broadmoor	S Salcedo 1900	R/R Conc SW 4"	40.00	4.00	17.78	SY	1901
Broadmoor	S Salcedo 2000	R/R Asph 5.5"	65.00	18.00	130.00	SY	2020
Broadmoor	S Salcedo 2000	R/R Conc SW 4"	69.00	4.00	30.67	SY	2001
Broadmoor	S Salcedo 2000	R/R Asph 5.5"	74.00	18.00	148.00	SY	2027
Broadmoor	S Salcedo 2100	R/R Asph 5.5"	8.00	5.00	4.44	SY	2100
Broadmoor	S Tonti 4400	R/R Conc SW 4"	8.00	4.00	3.56	SY	4400
Broadmoor	S Tonti 4400	R/R Asph 5.5"	50.00	12.00	66.67	SY	4431
Broadmoor	S Tonti 4900	R/R Curb	10.00	0.00	10.00	LF	4913
Broadmoor	S Tonti 4900	R/R Conc SW 4"	12.00	4.00	5.33	SY	4913
Broadmoor	S Tonti 5000	R/R Conc SW 4"	12.00	3.00	4.00	SY	5000
Broadmoor	S Tonti 5000	R/R Asph 5.5"	93.00	25.00	258.33	SY	5001
Broadmoor	S White 1700	R/R Conc SW 4"	12.00	4.00	5.33	SY	1707
Broadmoor	S White 1700	R/R Conc SW 4"	9.00	4.00	4.00	SY	1717
Broadmoor	S White 1700	R/R Conc SW 4"	40.00	4.00	17.78	SY	1701
Broadmoor	South Derbigny 4000	R/R Asph 5.5"	135.00	6.00	90.00	SY	4022 to 4000
Broadmoor	South Derbigny 4000	R/R Conc SW 4"	75.00	4.00	33.33	SY	4001
Broadmoor	South Derbigny 4000	R/R Conc SW 4"	44.00	4.00	21.33	SY	4051
Broadmoor	South Derbigny 4000	R/R Conc SW 4"	51.00	4.00	22.67	SY	4050
Broadmoor	South Derbigny 4000	R/R Asph 5.5"	40.00	26.00	115.56	SY	4050
Broadmoor	South Derbigny 4000	R/R Conc SW 4"	9.00	4.00	4.00	SY	4018
Broadmoor	South Derbigny 4000	R/R Conc SW 4"	41.00	4.00	18.22	SY	4000
Broadmoor	South Derbigny 4000	R/R Asph 5.5"	110.00	6.00	73.33	SY	4050 to 4022
Broadmoor	South Derbigny 4100	R/R Conc SW 4"	107.00	4.00	47.56	SY	Opposite 4112
Broadmoor	South Derbigny 4100	R/R Conc SW 4"	8.00	4.00	3.56	SY	4140
Broadmoor	South Derbigny 4100	R/R Conc SW 4"	27.00	4.00	12.00	SY	4139
Broadmoor	South Derbigny 4100	R/R Asph 5.5"	132.00	6.00	88.00	SY	4140 to 4120
Broadmoor	South Derbigny 4100	R/R Conc SW 4"	38.00	4.00	16.69	SY	4122

Broadmoor

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Broadmoor	South Derbigny 4100	R/R Conc SW 4"	45.00	4.00	20.00	SY	4112
Broadmoor	South Derbigny 4100	R/R Asph 5.5"	99.00	6.00	66.00	SY	4120 to 4100
Broadmoor	South Derbigny 4100	R/R Asph 5.5"	47.00	23.00	120.11	SY	Intersection at General Taylor
Broadmoor	South Derbigny 4100	R/R Conc SW 4"	23.00	4.00	10.22	SY	4120
Broadmoor	South Derbigny 4200	R/R Asph 5.5"	39.00	11.00	47.67	SY	4228
Broadmoor	South Derbigny 4200	R/R Asph 5.5"	32.00	11.00	39.11	SY	Opposite 4200
Broadmoor	South Derbigny 4200	R/R Conc SW 4"	20.00	4.00	8.89	SY	4211
Broadmoor	South Derbigny 4200	R/R Conc SW 4"	20.00	4.00	8.89	SY	4200
Broadmoor	South Derbigny 4200	R/R Conc SW 4"	45.00	4.00	20.00	SY	4212
Broadmoor	South Derbigny 4200	R/R Conc SW 4"	4.00	4.00	1.78	SY	4219
Broadmoor	South Derbigny 4200	R/R Asph 5.5"	13.00	6.00	8.87	SY	4220
Broadmoor	South Derbigny 4200	R/R Conc SW 4"	24.00	4.00	10.67	SY	Opposite 4228
Broadmoor	South Derbigny 4300	R/R Conc SW 4"	26.00	4.00	11.56	SY	4301
Broadmoor	South Derbigny 4300	R/R Conc SW 4"	10.00	4.00	4.44	SY	Intersection at General Pershing (Southwest Quad)
Broadmoor	South Derbigny 4300	R/R Asph 5.5"	32.00	11.00	39.11	SY	4300
Broadmoor	South Derbigny 4300	HC Ramp @ Intersection	0.00	0.00	1.00	SY	Intersection at General Pershing (Southwest Quad)
Broadmoor	South Derbigny 4300	R/R Conc SW 4"	29.00	4.00	12.89	SY	4300
Broadmoor	South Derbigny 4300	R/R Asph 5.5"	17.00	11.00	20.78	SY	4300
Broadmoor	South Derbigny 4300	R/R Conc SW 4"	18.00	4.00	8.00	SY	4322
Broadmoor	South Derbigny 4300	R/R Asph 5.5"	15.00	11.00	18.33	SY	4322
Broadmoor	South Derbigny 4300	R/R Asph 5.5"	21.00	11.00	25.67	SY	4308
Broadmoor	South Derbigny 4300	R/R Asph 5.5"	30.00	22.00	73.33	SY	4305
Broadmoor	South Derbigny 4300	R/R Asph 5.5"	42.00	38.00	129.33	SY	Intersection at General Pershing
Broadmoor	South Derbigny 4300	R/R Conc SW 4"	10.00	4.00	4.44	SY	Intersection at General Pershing (Northwest Quad)
Broadmoor	South Derbigny 4300	HC Ramp @ Intersection	0.00	0.00	1.00	SY	Intersection at General Pershing (Northwest Quad)
Broadmoor	South Derbigny 4300	R/R Conc SW 4"	19.00	4.00	8.44	SY	4315
Broadmoor	South Galvez (EB) 4300	R/R Asph 5.5"	5.00	6.00	3.33	SY	Intersection at General Pershing
Broadmoor	South Galvez (EB) 4300	R/R Conc SW 4"	36.00	4.00	16.00	SY	4308

Broadmoor

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Broadmoor	South Galvez (EB) 4300	R/R Conc SW 4"	60.00	4.00	26.67	SY	4330
Broadmoor	South Galvez (WB) 4300	R/R Conc DW 6"	4.00	6.00	2.67	SY	4311
Broadmoor	South Galvez (WB) 4300	R/R Conc SW 4"	20.00	5.00	11.11	SY	4303
Broadmoor	South Galvez (WB) 4300	R/R Asp 5.5"	55.00	6.00	36.67	SY	4303
Broadmoor	South Galvez (WB) 4300	R/R Asp 5.5"	14.00	18.00	16.00	SY	Intersection at General Pershing (Southwest Quad at Median)
Broadmoor	South Galvez (WB) 4300	R/R Conc SW 4"	11.00	5.00	6.11	SY	4311
Broadmoor	South Galvez (WB) 4300	R/R Asp 5.5"	66.00	6.00	44.00	SY	4329
Broadmoor	South Galvez (WB) 4300	R/R Asp 5.5"	9.00	9.00	9.00	SY	4311
Broadmoor	South Galvez (WB) 4300	R/R Conc SW 4"	38.00	5.00	21.11	SY	4329
Broadmoor	South Galvez 3300	R/R Conc SW 4"	40.00	4.00	17.78	SY	3301
Broadmoor	South Galvez 3400	R/R Conc SW 4"	16.00	4.00	7.11	SY	3421
Broadmoor	South Galvez 3400	R/R Conc SW 4"	14.00	4.00	6.22	SY	3405
Broadmoor	South Galvez 3400	R/R Asp 5.5"	10.00	12.00	13.33	SY	3421
Broadmoor	South Galvez 3400	R/R Asp 5.5"	15.00	24.00	40.00	SY	3418
Broadmoor	South Galvez 3400	R/R Conc SW 4"	20.00	4.00	8.89	SY	3413
Broadmoor	South Galvez 3700	R/R Conc SW 4"	19.00	4.00	8.44	SY	3705
Broadmoor	South Galvez 3700	R/R Conc SW 4"	11.00	4.00	4.89	SY	3733
Broadmoor	South Galvez 3700	R/R Conc SW 4"	11.00	44.00	4.89	SY	3713
Broadmoor	South Galvez 3700	R/R Conc SW 4"	22.00	4.00	9.78	SY	3720
Broadmoor	South Galvez 3700	R/R Asp 5.5"	39.00	8.00	34.67	SY	Opposite 3735
Broadmoor	South Galvez 4100	R/R Conc SW 4"	89.00	4.00	39.56	SY	Opposite 4111
Broadmoor	South Galvez 4100	R/R Asp 5.5"	4.00	4.00	1.78	SY	Intersection at General Taylor (in Center of intersection)
Broadmoor	South Galvez 4100	R/R Conc SW 4"	9.00	4.00	4.00	SY	Intersection at General Taylor (Southwest Quad)
Broadmoor	South Galvez 4100	R/R Asp 5.5"	6.00	6.00	4.00	SY	Intersection at General Taylor (Southwest Quad)
Broadmoor	South Galvez 4100	R/R Asp 5.5"	27.00	5.00	15.00	SY	4103
Broadmoor	South Galvez 4200	R/R Asp 5.5"	19.00	9.00	19.00	SY	4227
Broadmoor	South Galvez 4200	R/R Asp 5.5"	45.00	49.00	197.00	SY	Intersection at Milan
Broadmoor	South Galvez 4200	R/R Conc SW 4"	4.00	4.00	1.78	SY	4202
Broadmoor	South Galvez 4200	R/R Asp 5.5"	36.00	18.00	72.00	SY	4205
Broadmoor	South Galvez 4200	R/R Asp 5.5"	21.00	24.00	56.00	SY	4215



Broadmoor

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Broadmoor	South Galvez 4200	R/R Asph 5.5"	10.00	9.00	10.00	SY	4221
Broadmoor	South Galvez 4200	R/R Conc SW 4"	10.00	4.00	4.44	SY	4217
Broadmoor	South Galvez 4200	R/R Asph 5.5"	10.00	9.00	10.00	SY	4210
Broadmoor	South Galvez 4200	R/R Conc SW 4"	8.00	4.00	3.56	SY	4221
Broadmoor	South Roman 3300	R/R Conc SW 4"	56.00	4.00	24.89	SY	3330
Broadmoor	South Roman 3300	R/R Conc SW 4"	33.00	4.00	14.67	SY	3300
Broadmoor	South Roman 3300	R/R Asph 5.5"	10.00	8.00	8.89	SY	3300
Broadmoor	South Roman 3300	R/R Asph 5.5"	10.00	7.00	7.78	SY	3301
Broadmoor	South Roman 3300	R/R Conc SW 4"	20.00	4.00	8.89	SY	3331
Broadmoor	South Roman 3300	R/R Asph 5.5"	32.00	13.00	46.22	SY	3331
Broadmoor	South Roman 3600	R/R Conc SW 4"	30.00	4.00	13.33	SY	Opposite 3618
Broadmoor	South Roman 3600	R/R Conc SW 4"	32.00	4.00	14.22	SY	3600
Broadmoor	South Roman 3600	R/R Conc SW 4"	50.00	4.00	22.22	SY	3601
Broadmoor	South Roman 3600	R/R Conc SW 4"	13.00	4.00	13.78	SY	3618
Broadmoor	South Roman 3600	R/R Conc SW 4"	37.00	4.00	16.44	SY	3610
Broadmoor	South Roman 3600	R/R Asph 5.5"	9.00	7.00	7.00	SY	Opposite 3618
Broadmoor	South Roman 3700	R/R Asph 5.5"	38.00	6.00	25.33	SY	3723
Broadmoor	South Roman 3700	R/R Conc SW 4"	33.00	4.00	14.67	SY	3726
Broadmoor	South Roman 3700	R/R Asph 5.5"	16.00	6.00	10.67	SY	3731
Broadmoor	South Roman 3700	R/R Asph 5.5"	29.00	6.00	19.33	SY	3739
Broadmoor	South Roman 3700	R/R Asph 5.5"	292.00	8.00	259.56	SY	3700 to 3740
Broadmoor	South Roman 3700	R/R Asph 5.5"	45.00	6.00	30.00	SY	3701
Broadmoor	South Roman 3700	R/R Conc SW 4"	48.00	4.00	21.33	SY	3701
Broadmoor	South Roman 3700	R/R Conc SW 4"	38.00	4.00	16.89	SY	3700
Broadmoor	South Roman 3700	R/R Asph 5.5"	14.00	10.00	15.56	SY	Intersection at Delachaise (in Center of intersection)
Broadmoor	South Roman 4200	R/R Conc Pvmt 8"	25.00	25.00	57.44	SY	Intersection at Milan (Southwest Quad)
Broadmoor	South Roman 4200	R/R Conc SW 4"	4.00	4.00	1.78	SY	4232
Broadmoor	South Roman 4200	R/R Asph 5.5"	17.00	12.00	22.67	SY	4202
Broadmoor	South Roman 4200	R/R Conc SW 4"	23.00	4.00	10.22	SY	4219
Broadmoor	South Roman 4200-3800	R/R Conc SW 4"	9.00	4.00	4.00	SY	4200 to 3800
Broadmoor	South Roman 4200-3800	R/R Conc Pvmt 8"	53.00	49.00	240.56	SY	Intersection at General Taylor
Broadmoor	South Roman 4200-3800	R/R Curb	5.00	0.00	5.00	LF	4200 to 3800

Broadmoor

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Broadmoor	South Roman 4200-3800	R/R Conc Pvmt 8"	26.00	8.00	23.11	SY	4200 to 3800
Broadmoor	South Roman 4300	R/R Conc SW 4"	8.00	4.00	3.56	SY	4323
Broadmoor	South Roman 4300	R/R Conc Pvmt 8"	30.00	8.00	26.67	SY	4323
Broadmoor	South Roman 4300	R/R Conc Pvmt 8"	27.00	31.00	81.00	SY	Intersection at General Pershing
Broadmoor	South Roman 4300	R/R Conc Pvmt 8"	20.00	12.00	26.67	SY	4320
Broadmoor	South Roman 4300	R/R Conc SW 4"	13.00	4.00	5.78	SY	4320
Broadmoor	South Roman 4300	R/R Conc Pvmt 8"	16.00	6.00	10.67	SY	4311
Broadmoor	South Roman 4300	R/R Conc Pvmt 8"	18.00	6.00	12.00	SY	4311
Broadmoor	South Roman 4300	R/R Conc SW 4"	4.00	4.00	1.78	SY	4316
Broadmoor	South Tonti 3500	R/R Asph 5.5"	10.00	8.00	8.89	SY	3514
Broadmoor	South Tonti 3500	R/R Conc SW 4"	28.00	4.00	12.44	SY	Opposite 3530
Broadmoor	South Tonti 3500	R/R Asph 5.5"	27.00	8.00	24.00	SY	3520
Broadmoor	South Tonti 3500	R/R Conc SW 4"	23.00	4.00	10.22	SY	3514
Broadmoor	South Tonti 3500	R/R Conc SW 4"	35.00	4.00	15.56	SY	3509
Broadmoor	South Tonti 3500	R/R Asph 5.5"	57.00	8.00	50.67	SY	3508
Broadmoor	South Tonti 3500	R/R Conc SW 4"	71.00	4.00	31.56	SY	Opposite 3501
Broadmoor	South Tonti 3500	R/R Asph 5.5"	19.00	19.00	28.11	SY	Intersection at Delachaise (Northwest Quad)
Broadmoor	South Tonti 3500	R/R Asph 5.5"	15.00	25.00	29.67	SY	Intersection at Delachaise (Southwest Quad)
Broadmoor	South Tonti 3500	R/R Asph 5.5"	40.00	41.00	134.22	SY	Intersection at General Taylor
Broadmoor	South Tonti 3500	R/R Asph 5.5"	20.00	8.00	17.78	SY	3519
Broadmoor	South Tonti 4100	R/R Curb	17.00	0.00	17.00	LF	Opposite 4100
Broadmoor	South Tonti 4100	R/R Asph 5.5"	15.00	23.00	38.33	SY	Intersection at Milan (Northeast Quad)
Broadmoor	South Tonti 4100	R/R Asph 5.5"	28.00	12.00	37.33	SY	4100
Broadmoor	South Tonti 4200	R/R Asph 5.5"	23.00	11.00	28.11	SY	4219
Broadmoor	South Tonti 4200	R/R Conc SW 4"	14.00	4.00	6.22	SY	4213
Broadmoor	South Tonti 4200	R/R Conc SW 4"	102.00	4.00	45.33	SY	4201
Broadmoor	South Tonti 4300	R/R Conc SW 4"	15.00	4.00	6.67	SY	4321
Broadmoor	South Tonti 4300	R/R Asph 5.5"	10.00	7.00	7.78	SY	4321
Broadmoor	South Tonti 4300	R/R Asph 5.5"	26.00	12.00	34.67	SY	4340
Broadmoor	South Tonti 4300	R/R Asph 5.5"	9.00	11.00	11.00	SY	4320

Broadmoor

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Broadmoor	South Tonti 4300	R/R Conc SW 4"	12.00	4.00	5.33	SY	4306
Broadmoor	South Tonti 4300	R/R Asph 5.5"	9.00	21.00	21.00	SY	4307
Broadmoor	South Tonti 4300	R/R Asph 5.5"	49.00	3.00	16.33	SY	4307
Broadmoor	South Tonti 4300	R/R Conc SW 4"	24.00	4.00	10.67	SY	4307
Broadmoor	South Tonti 4300	R/R Conc SW 4"	16.00	4.00	7.11	SY	4312
Broadmoor	Upperline 3000	R/R Conc SW 4"	7.00	4.00	3.11	SY	3001
Broadmoor	Upperline 3000	R/R Conc SW 4"	47.00	4.00	20.89	SY	Opposite 3022
Broadmoor	Upperline 3000	R/R Conc SW 4"	15.00	5.00	8.33	SY	3001
Broadmoor	Upperline 3000	R/R Asph 5.5"	16.00	14.00	24.89	SY	3001
Broadmoor	Upperline 3100	R/R Conc SW 4"	25.00	4.00	11.11	SY	3102
Broadmoor	Upperline 3100	R/R Asph 5.5"	27.00	12.00	36.00	SY	3120
Broadmoor	Upperline 3100	R/R Conc SW 4"	34.00	4.00	15.11	SY	3101
Broadmoor	Upperline 3100	R/R Conc SW 4"	10.00	4.00	4.44	SY	3121
Broadmoor	Upperline 3100	R/R Asph 5.5"	25.00	12.00	33.33	SY	Intersection at S. Roman
Broadmoor	Upperline 3200	R/R Conc SW 4"	22.00	4.00	9.78	SY	3223
Broadmoor	Upperline 3200	R/R Conc SW 4"	92.00	4.00	40.89	SY	Opposite 3232
Broadmoor	Upperline 3200	R/R Asph 5.5"	23.00	17.00	43.33	SY	3232
Broadmoor	Upperline 3200	R/R Conc SW 4"	43.00	4.00	19.11	SY	3200 to 3206
Broadmoor	Upperline 3200	R/R Curb	5.00	0.00	5.00	LF	3223
Broadmoor	Upperline 3200	R/R Conc SW 4"	64.00	4.00	28.44	SY	3217 to 3211
Broadmoor	Upperline 3200	R/R Asph 5.5"	15.00	6.00	10.00	SY	3210 at intersection of S. Prieur
Broadmoor	Upperline 3300	R/R Conc SW 4"	25.00	4.00	11.11	SY	3322
Broadmoor	Upperline 3300	R/R Asph 5.5"	18.00	6.00	12.00	SY	3322
Broadmoor	Upperline 3300	R/R Asph 5.5"	48.00	6.00	32.00	SY	3314
Broadmoor	Upperline 3300	R/R Asph 5.5"	25.00	10.00	27.78	SY	3300
Broadmoor	Upperline 3400	R/R Conc SW 4"	54.00	4.00	24.00	SY	3406
Broadmoor	Upperline 3700	R/R Asph 5.5"	118.00	21.00	275.33	SY	3712
Broadmoor	Walmsley 4000	R/R Conc Pvmt 8"	108.00	10.00	120.00	SY	4000
Broadmoor	Walmsley 4000	R/R Conc Pvmt 8"	40.00	12.00	53.33	SY	4031
Broadmoor	Walmsley 4000	R/R Conc Pvmt 8"	47.00	47.00	197.44	SY	Intersection at S. Dupre
Broadmoor	Walmsley 4100	R/R Conc SW 4"	22.00	4.00	9.78	SY	4100
Broadmoor	Walmsley 4100	R/R Conc Pvmt 8"	206.00	12.00	274.67	SY	4100 to 4127
Broadmoor	Walmsley 4100	R/R Conc SW 4"	47.00	4.00	20.89	SY	4127

Broadmoor

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Broadmoor	Walmsley 4200	R/R Conc SW 4"	12.00	4.00	5.33	SY	4200
Broadmoor	Walmsley 4200	R/R Asph 5.5"	12.00	15.00	20.00	SY	4220
Broadmoor	Walmsley 4200	R/R Asph 5.5"	48.00	48.00	208.00	SY	Intersection at S. Salcedo
Broadmoor	Walmsley 4300	R/R Conc SW 4"	12.00	4.00	5.33	SY	4312
Broadmoor	Walmsley 4300	R/R Conc Pvmt 8"	8.00	15.00	13.33	SY	4317
Broadmoor	Walmsley 4400	R/R Conc SW 4"	24.00	4.00	10.67	SY	4431
Broadmoor	Walmsley 4400	R/R Conc SW 4"	12.00	4.00	5.33	SY	4410
Broadmoor	Walmsley 4400	R/R Conc Pvmt 8"	8.00	15.00	13.33	SY	4420
Broadmoor	Walmsley 4500	R/R Asph 5.5"	125.00	13.00	180.56	SY	Opposite 4522
Broadmoor	Walmsley 4500	R/R Asph 5.5"	55.00	18.00	110.00	SY	4517
Broadmoor	Walmsley 4500	R/R Curb	100.00	0.00	100.00	LF	Opposite 4522
Broadmoor	Walmsley 4500	R/R Conc SW 4"	20.00	4.00	8.89	SY	4521