

Bywater

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Bywater	Alvar St 600	R/R Conc SW 4"	35.00	5.00	19.44	SY	623
Bywater	Alvar St 700	R/R Conc SW 4"	25.00	5.00	13.89	SY	727
Bywater	Burgundy St 4400	R/R Asph 5.5"	5.00	15.00	8.33	SY	4420
Bywater	Burgundy St 4400	R/R Asph 5.5"	5.00	15.00	8.33	SY	4420
Bywater	Clouet St 1000	R/R Asph 5.5"	10.00	20.00	22.22	SY	1005
Bywater	Clouet St 1000	R/R Asph 5.5"	20.00	18.00	40.00	SY	1047
Bywater	Clouet St 700	R/R Conc DW 6"	10.00	11.00	12.22	SY	719
Bywater	Clouet St 900	R/R Asph 5.5"	20.00	10.00	22.22	SY	Intersection at N Rampart
Bywater	Congress St 600	R/R Conc SW 4"	15.00	4.00	6.67	SY	607
Bywater	Congress St 600	R/R Conc SW 4"	20.00	4.00	8.89	SY	639
Bywater	Congress St 700	R/R Asph 5.5"	10.00	10.00	11.11	SY	710
Bywater	Congress St 700	R/R Asph 5.5"	10.00	10.00	11.11	SY	707
Bywater	Congress St 800	R/R Conc SW 4"	33.00	5.00	18.33	SY	817
Bywater	Dauphine St 2600	R/R Conc SW 4"	3.00	3.00	1.00	SY	2601
Bywater	Dauphine St 2800	R/R Conc SW 4"	20.00	5.00	11.11	SY	2821
Bywater	Dauphine St 3200	R/R Conc SW 4"	50.00	5.00	27.78	SY	3201
Bywater	Dauphine St 3300	R/R Asph 5.5"	14.00	8.00	12.44	SY	3322
Bywater	Dauphine St 3300	R/R Asph 5.5"	14.00	8.00	12.44	SY	3318
Bywater	Dauphine St 3300	R/R Asph 5.5"	14.00	8.00	12.44	SY	3312
Bywater	Dauphine St 3500	R/R Conc SW 4"	5.00	5.00	2.78	SY	3523
Bywater	Dauphine St 3800	R/R Asph 5.5"	10.00	10.00	11.11	SY	3826
Bywater	Dauphine St 4000	R/R Conc SW 4"	20.00	5.00	11.11	SY	4012
Bywater	Desire St 0600	R/R Asph 5.5"	15.00	15.00	25.00	SY	621
Bywater	Desire St 0700	HC Ramp @ Intersection	11.00	11.00	13.44	SY	Intersection at Royal
Bywater	France St 0600	R/R Asph 5.5"	4.00	6.00	2.67	SY	633
Bywater	France St 0600	HC Ramp @ Intersection	11.00	11.00	13.44	SY	Intersection at Royal
Bywater	France St 0800	R/R Conc SW 4"	4.00	4.00	1.78	SY	839
Bywater	France St 1900	R/R Asph 5.5"	15.00	8.00	13.33	SY	Intersection at N Prieur
Bywater	France St 1900	R/R Asph 5.5"	4.00	4.00	1.78	SY	1931
Bywater	France St 1900	R/R Conc SW 4"	27.00	4.00	12.00	SY	1934
Bywater	France St 1900	R/R Conc SW 4"	60.00	4.00	26.67	SY	1929
Bywater	France St 1900	R/R Asph 5.5"	42.00	6.00	28.00	SY	1929
Bywater	France St 1900	R/R Conc SW 4"	20.00	4.00	8.89	SY	1919
Bywater	France St 1900	R/R Asph 5.5"	10.00	10.00	11.11	SY	1906
Bywater	France St 1900	R/R Conc SW 4"	42.00	4.00	18.67	SY	1902

Bywater

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Bywater	France St 1900	R/R Conc SW 4"	24.00	4.00	10.67	SY	1906
Bywater	France St 2000	R/R Conc SW 4"	20.00	4.00	8.89	SY	2031
Bywater	France St 2000	R/R Conc SW 4"	9.00	4.00	4.00	SY	2012
Bywater	France St 2000	HC Ramp @ Intersection	9.00	9.00	9.00	SY	NE corner of N Johnson
Bywater	France St 2000	R/R Asph 5.5"	12.00	12.00	16.00	SY	2000
Bywater	France St 2000	R/R Asph 5.5"	6.00	6.00	4.00	SY	2012
Bywater	France St 2000	R/R Asph 5.5"	15.00	10.00	16.67	SY	2026
Bywater	France St 2000	R/R Asph 5.5"	12.00	24.00	32.00	SY	2032
Bywater	France St 2100	R/R Asph 5.5"	12.00	24.00	32.00	SY	2134
Bywater	France St 2100	R/R Asph 5.5"	20.00	24.00	53.33	SY	2112
Bywater	France St 2100	R/R Conc SW 4"	99.00	4.00	44.00	SY	2114
Bywater	France St 2200	HC Ramp @ Intersection	9.00	9.00	9.00	SY	2200
Bywater	France St 2200	HC Ramp @ Intersection	9.00	9.00	9.00	SY	2141
Bywater	France St 2200	R/R Asph 5.5"	24.00	20.00	53.33	SY	2210
Bywater	France St 2200	R/R Conc SW 4"	10.00	4.00	4.44	SY	2210
Bywater	Gallier St 0700	HC Ramp @ Intersection	11.00	11.00	13.44	SY	701
Bywater	Gallier St 0700	R/R Asph 5.5"	6.00	6.00	4.00	SY	710
Bywater	Gallier St 0800	R/R Asph 5.5"	10.00	10.00	11.11	SY	Intersection at Burgundy
Bywater	Gallier St 0800	R/R Conc SW 4"	20.00	4.00	8.89	SY	831
Bywater	Japonica St 1400	HC Ramp @ Intersection	11.00	11.00	13.44	SY	Intersection at N Robertson
Bywater	Kentucky St 1100	R/R Conc SW 4"	60.00	4.00	26.67	SY	1120
Bywater	Kentucky St 1200	R/R Conc SW 4"	32.00	4.00	14.22	SY	1222
Bywater	Kentucky St 1200	R/R Conc SW 4"	30.00	4.00	13.33	SY	1223
Bywater	Kentucky St 1400	R/R Conc SW 4"	25.00	4.00	11.11	SY	1421
Bywater	Kentucky St 1400	R/R Asph 5.5"	50.00	10.00	55.56	SY	1421
Bywater	Lesseps St 0900	R/R Asph 5.5"	25.00	25.00	69.44	SY	917
Bywater	Lesseps St 1000	R/R Conc SW 4"	60.00	5.00	33.33	SY	1001
Bywater	Lesseps St 1000	R/R Asph 5.5"	25.00	25.00	69.44	SY	1021
Bywater	Lesseps St 1300	R/R Conc SW 4"	50.00	4.00	22.22	SY	1301
Bywater	Lesseps St 1400	R/R Asph 5.5"	20.00	24.00	53.33	SY	1430
Bywater	Lesseps St 1400	R/R Conc SW 4"	40.00	4.00	17.78	SY	1411
Bywater	Lesseps St 1500	R/R Conc SW 4"	24.00	4.00	10.67	SY	1503
Bywater	Lesseps St 1500	R/R Conc SW 4"	60.00	4.00	26.67	SY	1541
Bywater	Lesseps St 1500	R/R Asph 5.5"	35.00	24.00	93.33	SY	1503
Bywater	Lesseps St 1700	HC Ramp @ Intersection	9.00	9.00	9.00	SY	Intersection at N Roman
Bywater	Lesseps St 1800	R/R Conc SW 4"	50.00	4.00	22.22	SY	1806

Bywater

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Bywater	Marais St 4400	R/R Conc SW 4"	24.00	4.00	10.67	SY	4440
Bywater	Marais St 4500	R/R Conc SW 4"	22.00	4.00	9.78	SY	4530
Bywater	Marais St 4500	R/R Asph 5.5"	18.00	18.00	36.00	SY	4535
Bywater	Marais St 4500	R/R Asph 5.5"	18.00	18.00	36.00	SY	4501
Bywater	Mazant St 0700	R/R Conc SW 4"	10.00	4.00	4.44	SY	738
Bywater	Mazant St 0700	R/R Conc DW 6"	12.00	3.00	4.00	SY	738
Bywater	Mazant St 0700	R/R Conc SW 4"	35.00	5.00	19.44	SY	725
Bywater	Montegut St 0700	HC Ramp @ Intersection	9.00	9.00	9.00	SY	701
Bywater	North Derbingy St 4300	R/R Conc SW 4"	8.00	4.00	3.56	SY	4330
Bywater	North Johnson 4100	R/R Asph 5.5"	63.00	16.00	112.00	SY	4111
Bywater	North Johnson 4100	R/R Conc SW 4"	24.00	4.00	10.67	SY	4118
Bywater	North Johnson 4200	R/R Conc SW 4"	75.00	4.00	33.33	SY	4230
Bywater	North Johnson 4200	R/R Asph 5.5"	42.00	18.00	84.00	SY	4240
Bywater	North Johnson 4200	R/R Conc SW 4"	34.00	4.00	15.11	SY	4219
Bywater	North Johnson 4200	R/R Asph 5.5"	15.00	18.00	30.00	SY	4218
Bywater	North Prieur St 4100	R/R Asph 5.5"	247.00	19.00	521.44	SY	4100
Bywater	North Prieur St 4200	R/R Asph 5.5"	280.00	19.00	591.11	SY	4200
Bywater	North Rampart St 2700	R/R Asph 5.5"	6.00	10.00	6.67	SY	2732
Bywater	North Rampart St 2800	R/R Conc SW 4"	10.00	4.00	4.44	SY	2827
Bywater	North Rampart St 4300	R/R Conc SW 4"	20.00	5.00	11.11	SY	4301
Bywater	North Rampart St 4500	R/R Conc Pvmt 8"	7.00	12.00	9.33	SY	4524
Bywater	North Rampart St 4500	R/R Conc SW 4"	4.00	4.00	1.78	SY	4510
Bywater	North Robertson St 4500	R/R Conc SW 4"	24.00	5.00	13.33	SY	4540
Bywater	North Robertson St 4500	R/R Conc SW 4"	16.00	4.00	7.11	SY	4521
Bywater	North Roman St 4300	R/R Conc SW 4"	40.00	4.00	17.78	SY	4330
Bywater	North Villere St 4300	R/R Conc SW 4"	8.00	4.00	3.56	SY	4301
Bywater	North Villere St 4300	R/R Asph 5.5"	25.00	12.00	33.33	SY	4330
Bywater	North Villere St 4300	R/R Conc SW 4"	66.00	4.00	29.33	SY	4331
Bywater	North Villere St 4400	R/R Conc SW 4"	58.00	4.00	25.78	SY	4441
Bywater	Pauline ST 0800	R/R Asph 5.5"	15.00	26.00	43.33	SY	840
Bywater	Port St 0600	R/R Asph 5.5"	20.00	24.00	53.33	SY	Intersection at Architect
Bywater	Port St 0600	R/R Asph 5.5"	8.00	8.00	7.11	SY	Intersection at Charters
Bywater	Port St 0800	R/R Asph 5.5"	10.00	8.00	8.89	SY	827
Bywater	Royal ST 2600	R/R Conc SW 4"	10.00	5.00	5.56	SY	2605
Bywater	Royal ST 2600	R/R Conc SW 4"	15.00	5.00	8.33	SY	2624
Bywater	Royal ST 2700	R/R Conc SW 4"	20.00	5.00	11.11	SY	2729

Bywater

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Bywater	Royal ST 2700	R/R Conc SW 4"	5.00	5.00	2.78	SY	2727
Bywater	Royal ST 2700	R/R Conc SW 4"	10.00	5.00	5.56	SY	2727
Bywater	Royal ST 2800	R/R Conc SW 4"	30.00	5.00	16.67	SY	2833
Bywater	Royal ST 2800	R/R Conc SW 4"	40.00	5.00	22.22	SY	2831
Bywater	Royal ST 2800	R/R Conc SW 4"	10.00	5.00	5.56	SY	2800
Bywater	Royal St 3000	R/R Conc SW 4"	15.00	5.00	8.33	SY	3028
Bywater	Royal St 3000	R/R Conc SW 4"	52.00	4.00	23.11	SY	3001
Bywater	Royal St 3200	R/R Conc SW 4"	4.00	5.00	2.22	SY	3230
Bywater	Royal St 3400	R/R Conc SW 4"	25.00	4.00	11.11	SY	3430
Bywater	Royal St 4000	R/R Conc SW 4"	30.00	5.00	16.67	SY	4011
Bywater	Royal St 4100	R/R Conc SW 4"	50.00	4.00	22.22	SY	4130
Bywater	Royal St 4200	R/R Conc SW 4"	8.00	4.00	3.56	SY	4219
Bywater	Royal St 4200	R/R Conc SW 4"	80.00	4.00	35.56	SY	4213
Bywater	St Ferdinand 0600	R/R Conc SW 4"	8.00	5.00	4.44	SY	609
Bywater	St Ferdinand 0600	HC Ramp @ Intersection	12.00	12.00	16.00	SY	635
Bywater	St Ferdinand 0600	R/R Conc SW 4"	15.00	5.00	8.33	SY	615
Bywater	St Ferdinand 0900	R/R Asph 5.5"	20.00	8.00	17.78	SY	930
Bywater	Urquhart St 4300	R/R Asph 5.5"	65.00	16.00	115.56	SY	4317
Bywater	Urquhart St 4300	R/R Conc SW 4"	100.00	4.00	44.44	SY	4317
Bywater	Urquhart St 4400	R/R Asph 5.5"	20.00	19.00	42.22	SY	4400