

Dillard

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Dillard	Allen 4400	R/R Conc SW 4"	5.00	4.00	2.22	SY	4416
Dillard	Allen 4400	R/R Conc SW 4"	5.00	4.00	2.22	SY	4428
Dillard	Allen 4500	R/R Conc Pvmt 8"	37.00	10.00	41.11	SY	4538
Dillard	Allen 4500	R/R Conc SW 4"	22.00	4.00	9.78	SY	4537
Dillard	Allen 4500	R/R Conc SW 4"	22.00	4.00	9.78	SY	4524 to 4526
Dillard	Allen 4500	R/R Conc Pvmt 8"	33.00	17.00	62.33	SY	4518
Dillard	Allen 4500	R/R Conc SW 4"	31.00	4.00	13.78	SY	4514
Dillard	Allen 4500	R/R Conc Pvmt 8"	8.00	4.00	3.56	SY	4508
Dillard	Allen 4600	R/R Conc SW 4"	5.00	4.00	2.22	SY	Intersection at Carnot
Dillard	Allen 4600	R/R Conc Pvmt 8"	10.00	5.00	5.56	SY	Intersection at Carnot
Dillard	Allen 4600	R/R Conc Pvmt 8"	7.00	4.00	3.11	SY	4634
Dillard	Allen 4600	R/R Conc Pvmt 8"	32.00	4.00	14.22	SY	4618
Dillard	Allen 4600	HC Ramp @ Intersection	12.00	12.00	16.00	SY	Intersection at Carnot
Dillard	Allen 4700	R/R Conc SW 4"	25.00	4.00	11.11	SY	4719
Dillard	Allen 4700	R/R Conc SW 4"	46.00	4.00	20.44	SY	Opposite 4730 to 4738
Dillard	Allen 4700	R/R Conc Pvmt 8"	55.00	23.35	142.69	SY	Intersection at Brutus
Dillard	Allen 4800	R/R Conc SW 4"	73.00	4.00	32.44	SY	4805 to 4811
Dillard	Allen 4800	R/R Conc SW 4"	31.00	4.00	13.78	SY	4837
Dillard	Allen 4800	R/R Conc DW 6"	14.00	4.00	6.22	SY	4837
Dillard	Allen 4800	R/R Conc SW 4"	75.00	4.00	33.33	SY	4824 to 4838
Dillard	Allen 4800	R/R Conc SW 4"	10.00	4.00	4.44	SY	4827
Dillard	Annette 3300	R/R Asph 5.5"	6.00	10.00	6.67	SY	3301
Dillard	Annette 3300	R/R Asph 5.5"	9.00	10.00	10.00	SY	3334
Dillard	Annette 3400	R/R Asph 5.5"	20.00	4.00	8.89	SY	3400 to 3408
Dillard	Annette 4400	R/R Conc SW 4"	5.00	4.00	2.22	SY	Intersection at Lombard
Dillard	Annette 4400	R/R Conc Pvmt 8"	33.00	10.00	36.67	SY	4423
Dillard	Annette 4400	HC Ramp @ Intersection	12.00	12.00	16.00	SY	Intersection at Lombard
Dillard	Annette 4400	R/R Conc SW 4"	5.00	4.00	2.22	SY	Intersection at Lombard
Dillard	Annette 4400	R/R Conc SW 4"	9.00	4.00	4.00	SY	Intersection at Lombard
Dillard	Annette 4400	R/R Conc Pvmt 8"	23.00	7.00	17.89	SY	Intersection at Lombard
Dillard	Annette 4400	HC Ramp @ Intersection	12.00	12.00	16.00	SY	Intersection at Lombard
Dillard	Annette 4400	HC Ramp @ Intersection	12.00	12.00	16.00	SY	Intersection at Lombard
Dillard	Annette 4500	R/R Conc Pvmt 8"	28.00	18.00	56.00	SY	4520
Dillard	Annette 4500	R/R Conc Pvmt 8"	56.00	6.00	37.33	SY	Intersection at Sumpter
Dillard	Annette 4500	R/R Conc Pvmt 8"	82.00	7.00	63.78	SY	4500 to 4510

Dillard

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Dillard	Annette 4500	R/R Conc Pvmt 8"	30.00	18.00	60.00	SY	4531
Dillard	Annette 4500	R/R Conc Pvmt 8"	52.00	15.00	86.67	SY	4516
Dillard	Annette 4600	R/R Conc Pvmt 8"	6.00	6.00	4.00	SY	4606
Dillard	Annette 4600	R/R Conc Pvmt 8"	98.00	8.00	87.11	SY	4606 to 4614
Dillard	Annette 4600	R/R Conc SW 4"	17.00	4.00	7.56	SY	4623
Dillard	Annette 4600	R/R Conc DW 6"	12.00	4.00	5.33	SY	4623
Dillard	Annette 4600	R/R Conc SW 4"	5.00	4.00	2.22	SY	4630
Dillard	Annette 4600	R/R Conc Pvmt 8"	4.00	13.00	5.78	SY	4625
Dillard	Annette 4600	R/R Conc Pvmt 8"	54.00	7.00	42.00	SY	Intersection at Carnot
Dillard	Annette 4600	R/R Conc SW 4"	8.00	4.00	3.56	SY	4606
Dillard	Annette 4700	R/R Conc SW 4"	5.00	4.00	2.22	SY	4710
Dillard	Annette 4700	R/R Conc Pvmt 8"	64.00	17.00	120.89	SY	4711
Dillard	Annette 4700	R/R Conc Pvmt 8"	36.00	23.00	92.00	SY	4704
Dillard	Annette 4700	R/R Conc SW 4"	9.00	4.00	4.00	SY	4735
Dillard	Annette 4700	R/R Conc SW 4"	63.00	4.00	28.00	SY	4741
Dillard	Annette 4700	R/R Conc Pvmt 8"	20.00	44.00	97.78	SY	Intersection at Brutus
Dillard	Annette 4700	R/R Conc Pvmt 8"	15.00	8.00	13.33	SY	Intersection at Brutus
Dillard	Annette 4800	R/R Conc Pvmt 8"	166.00	25.00	461.11	SY	4818 to 4838
Dillard	Annette 4800	R/R Conc Pvmt 8"	30.00	9.00	30.00	SY	4811 to 4814
Dillard	Annette 4800	R/R Conc SW 4"	10.00	4.00	4.44	SY	4800
Dillard	Annette 4800	R/R Conc SW 4"	5.00	4.00	2.22	SY	4814
Dillard	Annette 4800	R/R Conc SW 4"	15.00	4.00	6.67	SY	4805
Dillard	Benefit 1800	R/R Curb	4.00	0.00	4.00	LF	1866
Dillard	Benefit 1800	R/R Curb	3.00	0.00	3.00	LF	1876
Dillard	Benefit 1800	R/R Asph 5.5"	29.00	24.00	77.33	SY	1812
Dillard	Benefit 2100	R/R Conc SW 4"	12.00	4.00	5.33	SY	2156
Dillard	Brutus 1800	R/R Conc SW 4"	36.00	4.00	16.00	SY	1845
Dillard	Brutus 1800	R/R Conc SW 4"	21.00	4.00	9.33	SY	1871
Dillard	Brutus 1800	R/R Conc SW 4"	24.00	4.00	10.67	SY	1831
Dillard	Brutus 1800	R/R Conc SW 4"	17.00	4.00	7.56	SY	1857
Dillard	Brutus 1900	R/R Asph 5.5"	96.00	12.00	128.00	SY	1966 to 1960
Dillard	Brutus 1900	R/R Conc SW 4"	38.00	4.00	16.89	SY	1937
Dillard	Brutus 1900	R/R Conc SW 4"	25.00	4.00	11.11	SY	1901
Dillard	Brutus 1900	R/R Conc SW 4"	15.00	4.00	6.67	SY	1917
Dillard	Brutus 1900	R/R Conc SW 4"	66.00	4.00	29.33	SY	1969
Dillard	Brutus 2000	R/R Asph 5.5"	27.00	7.00	21.00	SY	Opposite 2042

Dillard

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Dillard	Brutus 2000	R/R Asph 5.5"	8.00	9.00	8.00	SY	2017
Dillard	Brutus 2000	R/R Conc SW 4"	10.00	4.00	4.44	SY	2038
Dillard	Brutus 2000	R/R Conc SW 4"	24.00	4.00	10.67	SY	2088
Dillard	Brutus 2000	R/R Conc SW 4"	31.00	4.00	13.78	SY	2000
Dillard	Brutus 2100	R/R Conc SW 4"	39.00	4.00	17.33	SY	2187
Dillard	Brutus 2100	R/R Conc SW 4"	25.00	4.00	11.11	SY	2117
Dillard	Brutus 2100	R/R Asph 5.5"	70.00	10.00	77.78	SY	2137
Dillard	Brutus 2100	R/R Conc SW 4"	21.00	4.00	9.33	SY	2138
Dillard	Bruxelles 3400	R/R Asph 5.5"	12.00	9.00	12.00	SY	3432
Dillard	Bruxelles 3400	R/R Conc SW 4"	18.00	4.00	8.00	SY	3401
Dillard	Bruxelles 3400	R/R Asph 5.5"	10.00	8.00	8.89	SY	3424
Dillard	Bruxelles 3400	R/R Asph 5.5"	8.00	8.00	7.11	SY	3428
Dillard	Bruxelles 3400	R/R Asph 5.5"	15.00	8.00	13.33	SY	3430
Dillard	Bruxelles 3500	R/R Conc SW 4"	10.00	4.00	4.44	SY	3501
Dillard	Bruxelles 3500	R/R Asph 5.5"	4.00	8.00	3.56	SY	3515
Dillard	Bruxelles 3500	R/R Asph 5.5"	7.00	5.00	3.89	SY	3501
Dillard	Bruxelles 3600	R/R Asph 5.5"	10.00	12.00	13.33	SY	Intersection at Sere
Dillard	Bruxelles 3600	R/R Conc SW 4"	20.00	4.00	8.89	SY	3618
Dillard	Bruxelles 3600	R/R Conc SW 4"	40.00	4.00	17.78	SY	3639
Dillard	Bruxelles 3700	R/R Asph 5.5"	6.00	4.00	2.67	SY	Intersection at St. Denis
Dillard	Bruxelles 3700	R/R Asph 5.5"	4.00	6.00	2.67	SY	Intersection at St. Denis
Dillard	Bruxelles 3700	R/R Conc SW 4"	12.00	4.00	5.33	SY	3710
Dillard	Bruxelles 3700	R/R Conc SW 4"	12.00	4.00	5.33	SY	3702
Dillard	Bruxelles 3700	R/R Conc SW 4"	12.00	4.00	5.33	SY	3703
Dillard	Bruxelles 3700	R/R Conc SW 4"	12.00	3.00	4.00	SY	3724
Dillard	Bruxelles 3800	R/R Asph 5.5"	5.00	16.00	8.89	SY	Intersection at Foy
Dillard	Bruxelles 3800	R/R Asph 5.5"	6.00	8.00	5.33	SY	Intersection at Milton
Dillard	Bruxelles 3800	R/R Asph 5.5"	6.00	16.00	10.67	SY	3837
Dillard	Bruxelles 3800	R/R Conc SW 4"	16.00	4.00	7.11	SY	3839
Dillard	Carnot 1800	R/R Asph 5.5"	7.00	11.00	8.56	SY	1873
Dillard	Carnot 1800	R/R Conc SW 4"	18.00	4.00	8.00	SY	1867
Dillard	Carnot 1800	R/R Asph 5.5"	4.00	4.00	1.78	SY	1866
Dillard	Carnot 1800	R/R Conc SW 4"	30.00	4.00	13.33	SY	1888
Dillard	Carnot 1900	R/R Conc SW 4"	34.00	4.00	15.11	SY	1940
Dillard	Carnot 1900	R/R Conc SW 4"	10.00	4.00	4.44	SY	1988
Dillard	Carnot 1900	R/R Conc SW 4"	18.00	4.00	8.00	SY	1968

Dillard

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Dillard	Carnot 2000	R/R Conc SW 4"	52.00	4.00	23.11	SY	2087
Dillard	Carnot 2000	R/R Conc SW 4"	17.00	4.00	7.56	SY	2041
Dillard	Carnot 2000	R/R Asph 5.5"	24.00	18.00	48.00	SY	2030
Dillard	Carnot 2000	R/R Asph 5.5"	32.00	8.00	28.44	SY	2015
Dillard	Carnot 2000	R/R Asph 5.5"	11.00	10.00	12.22	SY	2007
Dillard	Carnot 2000	R/R Conc SW 4"	6.00	4.00	2.67	SY	2055
Dillard	Carnot 2000	R/R Asph 5.5"	24.00	18.00	48.00	SY	2030
Dillard	Carnot 2100	R/R Conc SW 4"	19.00	4.00	8.44	SY	2115
Dillard	Carnot 2100	R/R Conc SW 4"	32.00	4.00	14.22	SY	2125
Dillard	Carnot 2100	R/R Conc SW 4"	51.00	4.00	22.67	SY	2137
Dillard	Carnot 2100	R/R Conc SW 4"	16.00	4.00	7.11	SY	2151
Dillard	Carnot 2100	R/R Asph 5.5"	10.00	12.00	13.33	SY	2151
Dillard	Carnot 2100	R/R Conc SW 4"	44.00	4.00	19.56	SY	2188
Dillard	Carnot 2100	R/R Conc SW 4"	36.00	4.00	16.00	SY	2107
Dillard	Carnot 2100	R/R Asph 5.5"	9.00	6.00	6.00	SY	2100
Dillard	Carnot 2100	R/R Conc SW 4"	20.00	4.00	8.89	SY	2187
Dillard	Caton 2000	R/R Conc SW 4"	19.00	5.00	10.56	SY	2091
Dillard	Caton 2000	R/R Conc SW 4"	6.00	5.00	3.33	SY	2085
Dillard	Caton 2000	R/R Conc SW 4"	13.00	5.00	7.22	SY	2050
Dillard	Caton 2000	R/R Asph 5.5"	23.00	11.00	28.11	SY	2050
Dillard	Caton 2000	R/R Conc SW 4"	5.00	5.00	2.78	SY	2050
Dillard	Caton 2000	R/R Asph 5.5"	36.00	12.00	48.00	SY	2050
Dillard	Caton 2000	Adjust CB/MH	0.00	0.00	1.00	EA	2050
Dillard	Caton 2000	Adjust CB/MH	0.00	0.00	1.00	EA	2071
Dillard	Caton 2100	R/R Conc SW 4"	40.00	5.00	22.22	SY	2121
Dillard	Caton 2100	R/R Asph 5.5"	95.00	25.00	263.89	SY	2151 to 2199
Dillard	Caton 2100-1	R/R Conc SW 4"	17.00	5.00	9.44	SY	2105
Dillard	Caton 2100-1	R/R Curb	18.00	0.00	18.00	LF	2105
Dillard	Caton 2100-1	R/R Asph 5.5"	12.00	14.00	18.67	SY	2105
Dillard	Caton Ct 1600	R/R Conc Pvmt 8"	62.00	26.00	179.11	SY	1600
Dillard	Caton Ct 1600	R/R Conc Pvmt 8"	62.00	26.00	179.11	SY	1627 to 1629
Dillard	Caton Ct 1600	R/R Conc Pvmt 8"	19.00	19.00	40.11	SY	1659
Dillard	Caton Ct 1600	R/R Conc Pvmt 8"	43.00	20.00	95.56	SY	1659
Dillard	Caton Ct 1600	R/R Conc SW 4"	27.00	5.00	15.00	SY	1659
Dillard	Caton Ct 1600	R/R Conc Pvmt 8"	47.00	13.00	67.89	SY	Opposite 1619
Dillard	Churchill Dr (EB) 1600	R/R Conc SW 4"	82.00	4.00	36.44	SY	1648

Dillard

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Dillard	Churchill Dr 1600	R/R Asph 5.5"	5.00	6.00	3.33	SY	1650
Dillard	Churchill Dr 1600	R/R Conc SW 4"	28.00	4.00	12.44	SY	1698
Dillard	Churchill Dr 1600	R/R Conc SW 4"	14.00	4.00	6.22	SY	1697
Dillard	Foy 1600	R/R Asph 5.5"	14.00	11.00	17.11	SY	Opposite 1614
Dillard	Foy 1600	R/R Conc SW 4"	103.00	4.00	45.78	SY	1601
Dillard	Foy 1600	R/R Conc SW 4"	23.00	4.00	10.22	SY	1643
Dillard	Foy 2100	R/R Conc SW 4"	20.00	4.00	8.89	SY	2150
Dillard	Foy 2100	R/R Conc SW 4"	48.00	4.00	21.33	SY	2105
Dillard	Foy 2100	R/R Conc SW 4"	9.00	4.00	40.00	SY	2110
Dillard	Foy 2100	Adjust CB/MH	0.00	0.00	1.00	EA	2105
Dillard	Frenchmen 3300	R/R Conc SW 4"	32.00	5.00	17.78	SY	3312 to 3306
Dillard	Frenchmen 3300	R/R Curb	6.00	0.00	6.00	LF	Intersection at Humanity
Dillard	Frenchmen 3300	R/R Conc SW 4"	21.00	5.00	11.67	SY	3316
Dillard	Frenchmen 3300	R/R Conc Pvmt 8"	8.00	8.00	7.11	SY	3301
Dillard	Frenchmen 3400	R/R Conc Pvmt 8"	9.00	17.00	170.00	SY	3410
Dillard	Frenchmen 3400	R/R Conc Pvmt 8"	8.00	27.00	24.00	SY	3424
Dillard	Frenchmen 3400	R/R Conc SW 4"	10.00	5.00	5.56	SY	3424
Dillard	Frenchmen 3500	R/R Conc Pvmt 8"	48.00	10.50	56.00	SY	Intersection at Lafreniere
Dillard	Frenchmen 3500	R/R Conc SW 4"	10.00	5.00	5.56	SY	Intersection at Lafreniere
Dillard	Frenchmen 3500	R/R Conc SW 4"	12.00	5.00	6.67	SY	3511 to 3507
Dillard	Frenchmen 3500	R/R Conc SW 4"	16.00	5.00	8.89	SY	3523
Dillard	Frenchmen 3500	R/R Conc SW 4"	12.00	5.00	6.67	SY	3540
Dillard	Frenchmen 3500	HC Ramp @ Intersection	12.00	12.00	16.00	SY	Intersection at Lafreniere
Dillard	Frenchmen 3700	R/R Conc Pvmt 8"	44.00	34.00	166.22	SY	Intersection at St. Denis
Dillard	Frenchmen 3700	HC Ramp @ Intersection	12.00	12.00	16.00	SY	Intersection at St. Denis
Dillard	Frenchmen 3700	R/R Conc SW 4"	36.00	5.00	20.00	SY	3715
Dillard	Frenchmen 3700	R/R Conc SW 4"	10.00	5.00	5.56	SY	Intersection at St. Denis
Dillard	Frenchmen 3700	HC Ramp @ Intersection	12.00	12.00	16.00	SY	Intersection at St. Denis
Dillard	Frenchmen 3700	R/R Conc SW 4"	6.00	5.00	3.33	SY	Intersection at St. Denis
Dillard	Frenchmen 3800	R/R Conc SW 4"	3.00	5.00	1.67	SY	Intersection at Milton
Dillard	Frenchmen 3800	R/R Conc SW 4"	50.00	5.00	27.78	SY	3805
Dillard	Frenchmen 3800	R/R Conc Pvmt 8"	2.00	7.00	1.56	SY	3835
Dillard	Frenchmen 3800	HC Ramp @ Intersection	12.00	12.00	16.00	SY	Intersection at Milton
Dillard	Frenchmen 3900	R/R Conc SW 4"	10.00	5.00	5.56	SY	Intersection at Caton
Dillard	Frenchmen 3900	R/R Conc SW 4"	16.00	5.00	8.89	SY	3989
Dillard	Frenchmen 3900	HC Ramp @ Intersection	12.00	12.00	16.00	SY	Intersection at Caton

Dillard

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Dillard	Frenchmen 4000	R/R Conc SW 4"	74.00	5.00	41.11	SY	4001
Dillard	Frenchmen 4000	R/R Conc SW 4"	20.00	5.00	11.11	SY	4037
Dillard	Frenchmen 4000	R/R Conc SW 4"	5.00	5.00	2.78	SY	Intersection at Senate
Dillard	Frenchmen 4000	HC Ramp @ Intersection	12.00	12.00	16.00	SY	Intersection at Senate
Dillard	Frenchmen 4100	R/R Asph 5.5"	70.00	8.00	62.22	SY	4135 to 4165
Dillard	Frenchmen 4100	R/R Asph 5.5"	6.00	6.00	4.00	SY	Intersection at Pelopidas
Dillard	Frenchmen 4300	R/R Conc SW 4"	46.00	4.00	20.44	SY	4390
Dillard	Frenchmen 4500	R/R Conc SW 4"	44.00	4.00	19.56	SY	Opposite 4510
Dillard	Frenchmen 4500	R/R Asph 5.5"	24.00	24.00	64.00	SY	4514
Dillard	Frenchmen 4500	R/R Conc SW 4"	78.00	4.00	34.67	SY	Opposite 4522 to 4540
Dillard	Frenchmen 4500	R/R Conc SW 4"	18.00	4.00	8.00	SY	4506
Dillard	Frenchmen 4600	R/R Asph 5.5"	8.00	6.00	5.33	SY	4603
Dillard	Frenchmen 4600	R/R Asph 5.5"	8.00	14.00	12.44	SY	4634
Dillard	Frenchmen 4600	R/R Conc SW 4"	8.00	4.00	3.56	SY	4622
Dillard	Frenchmen 4700	R/R Conc SW 4"	26.00	4.00	11.56	SY	4700
Dillard	Havana 3300	R/R Conc SW 4"	5.00	4.00	2.20	SY	3300
Dillard	Havana 3400	R/R Asph 5.5"	4.00	3.00	1.33	SY	3419
Dillard	Havana 3500	R/R Conc SW 4"	10.00	4.00	4.44	SY	3531
Dillard	Havana 3600	R/R Conc SW 4"	12.00	4.00	5.33	SY	3608
Dillard	Havana 3600	R/R Conc SW 4"	5.00	4.00	2.22	SY	3611
Dillard	Havana 3600	R/R Conc SW 4"	10.00	4.00	4.44	SY	3601
Dillard	Havana 3800	R/R Conc SW 4"	9.00	4.00	4.00	SY	3803
Dillard	Humanity 1900	R/R Conc Pvmt 8"	4.00	6.00	2.67	SY	1923
Dillard	Lafreniere 1600	R/R Conc SW 4"	24.00	4.00	10.67	SY	1614
Dillard	Lafreniere 1600	R/R Conc SW 4"	22.00	4.00	9.78	SY	1617 to 1619
Dillard	Lafreniere 1600	R/R Conc SW 4"	29.00	4.00	12.89	SY	1600
Dillard	Lafreniere 1600	R/R Asph 5.5"	8.00	8.00	7.11	SY	1620
Dillard	Lafreniere 1700	R/R Conc SW 4"	11.00	4.00	4.89	SY	1781
Dillard	Lafreniere 1700	R/R Conc SW 4"	12.00	4.00	5.33	SY	1724
Dillard	Lafreniere 1700	R/R Conc SW 4"	13.00	4.00	5.78	SY	1709
Dillard	Lafreniere 1900	R/R Asph 5.5"	88.00	18.00	176.00	SY	1927 to 1921
Dillard	Lafreniere 1900	R/R Asph 5.5"	13.00	5.00	7.22	SY	1922
Dillard	Lafreniere 2000	R/R Asph 5.5"	16.00	10.00	17.78	SY	2055
Dillard	Lafreniere 2000	R/R Conc SW 4"	10.00	4.00	4.44	SY	Opposite 2036
Dillard	Lafreniere 2000	R/R Conc SW 4"	10.00	4.00	4.44	SY	2048
Dillard	Lafreniere 2000	R/R Conc SW 4"	20.00	4.00	8.89	SY	2050

Dillard

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Dillard	Lafreniere 2000	R/R Conc SW 4"	8.00	4.00	3.56	SY	2037
Dillard	Lafreniere 2100	R/R Conc SW 4"	18.00	4.00	8.00	SY	2130
Dillard	Lafreniere 2100	R/R Conc SW 4"	38.00	4.00	16.89	SY	2169
Dillard	Lafreniere 2100	R/R Asph 5.5"	276.00	16.00	490.67	SY	2157 to 2199
Dillard	Lafreniere 2100	R/R Conc SW 4"	5.00	4.00	2.22	SY	2132
Dillard	Lafreniere 2100	R/R Conc SW 4"	9.00	4.00	4.00	SY	2101
Dillard	Lafreniere 2100	R/R Asph 5.5"	250.00	16.00	444.44	SY	2100 to 2132
Dillard	Lombard 1800	R/R Conc Pvmt 8"	42.00	6.00	28.00	SY	1821 to 1825
Dillard	Lombard 1800	R/R Conc SW 4"	20.00	4.00	8.89	SY	1801
Dillard	Lombard 1800	R/R Conc Pvmt 8"	16.00	17.00	30.22	SY	1818
Dillard	Lombard 1900	R/R Conc SW 4"	15.00	4.00	6.67	SY	1936
Dillard	Lombard 1900	R/R Conc Pvmt 8"	33.00	15.00	55.00	SY	1951
Dillard	Lombard 1900	R/R Conc SW 4"	16.00	4.00	7.11	SY	1963
Dillard	Lombard 1900	R/R Curb	2.00	0.00	2.00	LF	1925
Dillard	Lombard 1900	R/R Conc SW 4"	20.00	4.00	8.89	SY	1919
Dillard	Lombard 2000	R/R Conc SW 4"	12.00	4.00	5.33	SY	2059
Dillard	Lombard 2000	R/R Conc SW 4"	23.00	4.00	10.22	SY	2000
Dillard	Lombard 2000	R/R Conc SW 4"	33.00	4.00	14.67	SY	2038
Dillard	Lombard 2000	R/R Conc SW 4"	62.00	4.00	27.56	SY	2037 to 2019
Dillard	Lombard 2100	R/R Conc SW 4"	33.00	4.00	14.67	SY	2181 to 2141
Dillard	Lombard 2100	R/R Conc SW 4"	18.00	4.00	8.00	SY	2126
Dillard	Lombard 2100	R/R Conc SW 4"	58.00	4.00	25.78	SY	2114 to 2100
Dillard	Lombard 2100	R/R Conc SW 4"	76.00	4.00	33.78	SY	Opposite 2114 to 2100
Dillard	London Ave 0000	R/R Asph 5.5"	10.00	5.00	5.56	SY	Mid Block
Dillard	Mandolin 1800	R/R Conc SW 4"	40.00	4.00	17.78	SY	1800
Dillard	Mandolin 1900	R/R Conc SW 4"	17.00	4.00	7.56	SY	1909
Dillard	Mandolin 1900	R/R Conc SW 4"	20.00	4.00	8.89	SY	1987
Dillard	Mandolin 2100	R/R Conc SW 4"	20.00	4.00	8.89	SY	2175
Dillard	Mandolin 2100	R/R Conc SW 4"	8.00	4.00	3.56	SY	2165
Dillard	Mandolin 2100	R/R Conc SW 4"	73.00	4.00	32.44	SY	2135
Dillard	Milton 1600	R/R Asph 5.5"	8.00	12.00	10.67	SY	1658
Dillard	Milton 1600	R/R Asph 5.5"	10.00	15.00	16.67	SY	1600
Dillard	Milton 1600	R/R Asph 5.5"	21.00	6.00	14.00	SY	1600
Dillard	Milton 1600	R/R Asph 5.5"	20.00	10.00	22.22	SY	1616
Dillard	Milton 1600	R/R Conc SW 4"	52.00	4.00	23.11	SY	Opposite 1618
Dillard	Milton 1600	R/R Conc SW 4"	12.00	4.00	5.33	SY	1634

Dillard

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Dillard	Milton 1600	R/R Asph 5.5"	60.00	6.00	40.00	SY	Opposite 1618 to 1626
Dillard	Milton 2100	R/R Conc SW 4"	39.00	4.00	17.33	SY	2115
Dillard	Milton 2100	R/R Asph 5.5"	7.00	14.00	10.89	SY	2140
Dillard	Milton 2100	R/R Asph 5.5"	6.00	10.00	6.67	SY	2158
Dillard	Milton 2100	R/R Asph 5.5"	8.00	5.00	4.44	SY	2170
Dillard	Milton 2100	R/R Conc SW 4"	71.00	4.00	31.56	SY	2130 to 2100
Dillard	New Orleans 4500	R/R Conc SW 4"	23.00	4.00	10.22	SY	4519
Dillard	New Orleans 4500	R/R Conc SW 4"	23.00	4.00	10.22	SY	Opposite 4519
Dillard	New Orleans 4500	R/R Conc SW 4"	11.00	4.00	4.89	SY	Opposite 4511
Dillard	New Orleans 4500	R/R Conc SW 4"	10.00	4.00	4.44	SY	Intersection at Lombard
Dillard	New Orleans 4500	HC Ramp @ Intersection	12.00	12.00	16.00	SY	Intersection at Lombard
Dillard	New Orleans 4600	R/R Asph 5.5"	4.00	4.00	1.78	SY	4635
Dillard	New Orleans 4600	R/R Conc SW 4"	19.00	4.00	8.44	SY	4620
Dillard	New Orleans 4700	R/R Conc SW 4"	17.00	4.00	7.56	SY	4705 to 4701
Dillard	New Orleans 4700	R/R Asph 5.5"	6.00	6.00	4.00	SY	Intersection at Carnot
Dillard	New Orleans 4800	R/R Asph 5.5"	12.00	9.00	12.00	SY	4801
Dillard	New Orleans 4800	R/R Conc SW 4"	42.00	4.00	18.67	SY	4827
Dillard	New Orleans 4800	R/R Conc SW 4"	19.00	4.00	8.44	SY	4800
Dillard	Pauger 3800	R/R Conc SW 4"	20.00	4.00	8.89	SY	3880
Dillard	Pauger 3900	R/R Conc SW 4"	30.00	4.00	13.33	SY	3922
Dillard	Pauger 3900	R/R Conc SW 4"	15.00	4.00	6.67	SY	3950
Dillard	Pauger 4000	R/R Conc SW 4"	15.00	4.00	6.67	SY	4019
Dillard	Pauger 4000	R/R Conc SW 4"	25.00	4.00	11.11	SY	4025
Dillard	Pauger 4100	R/R Conc SW 4"	8.00	4.00	3.56	SY	4133
Dillard	Pauger 4100	R/R Asph 5.5"	7.00	6.00	4.67	SY	4135
Dillard	Pauger 4200	R/R Asph 5.5"	5.00	6.00	3.33	SY	Opposite 4234
Dillard	Pauger 4300	R/R Conc SW 4"	9.00	4.00	4.00	SY	4324
Dillard	Pauger 4400	R/R Curb	7.00	0.00	7.00	LF	Intersection at Lombard
Dillard	Pauger 4400	R/R Conc SW 4"	6.00	4.00	2.67	SY	4440
Dillard	Pauger 4400	Adjust CB/MH	0.00	0.00	1.00	EA	4436
Dillard	Pauger 4500	R/R Asph 5.5"	20.00	30.00	66.67	SY	Intersection at Sumpter
Dillard	Pauger 4500	R/R Conc SW 4"	13.00	4.00	5.78	SY	4522
Dillard	Pauger 4500	R/R Conc SW 4"	12.00	4.00	5.33	SY	4518
Dillard	Pauger 4500	R/R Conc SW 4"	18.00	4.00	8.00	SY	4510
Dillard	Pauger 4600	R/R Conc SW 4"	30.00	4.00	13.33	SY	4604 to 4616
Dillard	Pauger 4600	R/R Conc SW 4"	28.00	4.00	12.44	SY	4634

Dillard

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Dillard	Pauger 4700	R/R Conc SW 4"	9.00	4.00	4.00	SY	4733
Dillard	Pauger 4800	R/R Conc SW 4"	17.00	4.00	7.56	SY	4808
Dillard	Pauger 4800	R/R Conc SW 4"	12.00	4.00	5.33	SY	4817
Dillard	Pauger 4800	R/R Conc SW 4"	8.00	4.00	3.56	SY	4826
Dillard	Pauger 4800	R/R Conc SW 4"	29.00	4.00	12.89	SY	4837
Dillard	Pelopidas 1900	R/R Asph 5.5"	10.00	9.00	10.00	SY	1916
Dillard	Pelopidas 1900	R/R Asph 5.5"	25.00	21.00	58.33	SY	1910
Dillard	Pelopidas 1900	R/R Asph 5.5"	54.00	5.00	30.00	SY	1932
Dillard	Pelopidas 2000	R/R Conc SW 4"	12.00	4.00	5.33	SY	2056
Dillard	Pelopidas 2000	R/R Asph 5.5"	12.00	8.00	10.67	SY	2056
Dillard	Pelopidas 2100	R/R Asph 5.5"	18.00	10.00	20.00	SY	2182
Dillard	Pelopidas 2100	R/R Asph 5.5"	35.00	12.00	46.67	SY	2198
Dillard	Pelopidas 2100	R/R Asph 5.5"	50.00	7.00	38.89	SY	2190 to 2184
Dillard	Pleasure 1700	R/R Asph 5.5"	63.00	19.00	133.00	SY	1769 to 1773
Dillard	Pleasure 1700	R/R Conc SW 4"	16.00	4.00	7.11	SY	1765
Dillard	Pleasure 1800	R/R Conc SW 4"	21.00	4.00	9.33	SY	1856 to 1854
Dillard	Pleasure 1800	R/R Asph 5.5"	322.00	16.00	572.44	SY	1870 to 1851
Dillard	Pleasure 1800	R/R Conc SW 4"	30.00	4.00	13.33	SY	1867
Dillard	Pleasure 1800	R/R Conc SW 4"	20.00	4.00	8.89	SY	1852
Dillard	Pleasure 1900	R/R Asph 5.5"	6.00	6.00	4.00	SY	1998
Dillard	Pleasure 1900	R/R Asph 5.5"	232.00	16.00	412.44	SY	1998 to 1951
Dillard	Pleasure 1900	R/R Conc SW 4"	21.00	4.00	9.33	SY	1956
Dillard	Pleasure 1900	R/R Asph 5.5"	108.00	16.00	192.00	SY	1915 to 1900
Dillard	Pleasure 1900	R/R Asph 5.5"	62.00	16.00	110.22	SY	1940 to 1927
Dillard	Pleasure 1900	R/R Asph 5.5"	10.00	5.00	5.56	SY	1950
Dillard	Pleasure 2000	R/R Conc SW 4"	12.00	4.00	5.33	SY	2020
Dillard	Pleasure 2000	R/R Conc SW 4"	28.00	4.00	12.44	SY	2025
Dillard	Pleasure 2000	R/R Conc SW 4"	32.00	4.00	14.22	SY	2061
Dillard	Pleasure 2000	R/R Conc SW 4"	53.00	4.00	23.56	SY	2000
Dillard	Pleasure 2000	R/R Conc SW 4"	11.00	4.00	4.89	SY	2045
Dillard	Pleasure 2000	R/R Conc SW 4"	32.00	4.00	14.22	SY	2053
Dillard	Pleasure 2000	R/R Curb	8.00	0.00	8.00	LF	2045
Dillard	Pleasure 2100	R/R Asph 5.5"	102.00	19.00	215.33	SY	2149 to 2126
Dillard	Pleasure 2100	R/R Asph 5.5"	317.00	19.00	669.22	SY	2151 to 2199
Dillard	Pleasure 2100	R/R Conc SW 4"	13.00	4.00	5.78	SY	2158
Dillard	Pleasure 2100	R/R Conc SW 4"	26.00	4.00	11.56	SY	2115

Dillard

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Dillard	Pleasure 2100	R/R Conc SW 4"	36.00	4.00	16.00	SY	2123
Dillard	Rayne Dr. 4200	R/R Conc SW 4"	12.00	4.00	5.33	SY	4216
Dillard	Rayne Dr. 4200	R/R Conc SW 4"	16.00	4.00	7.11	SY	4207
Dillard	Rayne Dr. 4200	R/R Conc SW 4"	12.00	4.00	5.33	SY	4211
Dillard	Rayne Dr. 4200	R/R Conc SW 4"	12.00	4.00	5.33	SY	4215
Dillard	Rayne Dr. 4200	R/R Conc SW 4"	12.00	4.00	5.33	SY	4219
Dillard	Rayne Dr. 4200	R/R Conc SW 4"	30.00	4.00	13.33	SY	4209
Dillard	Rayne Dr. 4200	R/R Conc SW 4"	19.00	4.00	8.44	SY	4213
Dillard	Rayne Dr. 4200	R/R Asph 5.5"	8.00	8.00	7.11	SY	Intersection at Chruchill
Dillard	Rayne Dr. 4200	R/R Asph 5.5"	3.00	3.00	1.00	SY	Intersection at Chruchill
Dillard	Rayne Dr. 4200	R/R Asph 5.5"	18.00	16.00	32.00	SY	Intersection at Chruchill
Dillard	Rayne Dr. 4200	R/R Conc SW 4"	62.00	4.00	27.56	SY	4234
Dillard	Rayne Dr. 4200	R/R Conc SW 4"	29.00	4.00	12.89	SY	4230
Dillard	Rayne Dr. 4300	R/R Conc SW 4"	5.00	4.00	2.22	SY	4338
Dillard	Rayne Dr. 4300	R/R Conc Pvmt 8"	24.00	4.00	10.67	SY	4334
Dillard	Rayne Dr. 4300	R/R Conc SW 4"	16.00	4.00	7.11	SY	4305
Dillard	Republic 3300	R/R Asph 5.5"	6.00	6.00	4.00	SY	Intersection at Pleasure
Dillard	Republic 3300	R/R Conc SW 4"	26.00	4.00	11.56	SY	3398
Dillard	Republic 3300	R/R Asph 5.5"	18.00	5.00	10.00	SY	3323
Dillard	Republic 3600	R/R Conc SW 4"	10.00	4.00	4.44	SY	3618
Dillard	Republic 3600	R/R Conc SW 4"	13.00	4.00	5.78	SY	3619
Dillard	Republic 3700	R/R Asph 5.5"	20.00	10.00	22.22	SY	Intersection at Milton
Dillard	Senate 2000	R/R Conc SW 4"	15.00	4.00	6.67	SY	Opposite 2051
Dillard	Senate 2000	R/R Asph 5.5"	57.00	10.00	63.33	SY	2060 to 2080
Dillard	Senate 2000	R/R Conc SW 4"	15.00	4.00	6.67	SY	2081
Dillard	Senate 2000	R/R Asph 5.5"	82.00	24.00	218.67	SY	2051
Dillard	Senate 2100	R/R Asph 5.5"	17.00	20.00	37.78	SY	2198
Dillard	Senate 2100	R/R Asph 5.5"	11.00	10.00	12.22	SY	2141
Dillard	Senate 2100	R/R Conc SW 4"	26.00	5.00	14.44	SY	2100
Dillard	Senate 2100	R/R Conc SW 4"	20.00	4.00	8.89	SY	2151
Dillard	Sere 1600	R/R Asph 5.5"	9.00	5.00	5.00	SY	1662
Dillard	Sere 1600	R/R Conc SW 4"	14.00	4.00	6.22	SY	1688
Dillard	Sere 1600	R/R Asph 5.5"	20.00	20.00	44.44	SY	1637
Dillard	Sere 1600	R/R Asph 5.5"	9.00	20.00	20.00	SY	1637
Dillard	Sere 1600	R/R Asph 5.5"	19.00	11.00	23.22	SY	1631
Dillard	Sere 1600	R/R Conc SW 4"	17.00	4.00	7.56	SY	1638

Dillard

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Dillard	Sere 1600	R/R Conc SW 4"	7.00	4.00	3.11	SY	1614
Dillard	Sere 1600	R/R Conc SW 4"	7.00	4.00	3.11	SY	1670
Dillard	Sere 1700	R/R Asph 5.5"	18.00	8.00	16.00	SY	1730
Dillard	Sere 1700	R/R Conc SW 4"	9.00	4.00	4.00	SY	1709
Dillard	Sere 1700	R/R Conc SW 4"	17.00	4.00	7.56	SY	1716
Dillard	Sere 2000	R/R Conc SW 4"	10.00	4.00	4.44	SY	2054
Dillard	Sere 2000	R/R Conc SW 4"	72.00	4.00	32.00	SY	2000
Dillard	Sere 2100	R/R Conc SW 4"	42.00	4.00	18.67	SY	2120
Dillard	Sere 2100	R/R Conc SW 4"	18.00	4.00	8.00	SY	Opposite 2132
Dillard	St. Anthony 3200	R/R Curb	3.00	0.00	3.00	LF	Intersection at Humanity
Dillard	St. Anthony Ave 3300	R/R Conc SW 4"	15.00	4.00	6.67	SY	3328
Dillard	St. Anthony Ave 3300	R/R Conc SW 4"	24.00	4.00	10.67	SY	3342
Dillard	St. Anthony Ave 3300	R/R Curb	5.00	0.00	5.00	LF	Intersection at Humanity
Dillard	St. Anthony Ave 3300	R/R Conc SW 4"	25.00	4.00	11.11	SY	3312
Dillard	St. Anthony Ave 3400	R/R Asph 5.5"	12.00	14.00	18.67	SY	Intersection at Lafreniere
Dillard	St. Anthony Ave. 3500	R/R Conc SW 4"	27.00	4.00	12.00	SY	3523 to 3525
Dillard	St. Anthony Ave. 3500	R/R Conc SW 4"	40.00	4.00	17.78	SY	3533 to 3535
Dillard	St. Anthony Ave. 3500	R/R Conc SW 4"	30.00	4.00	13.33	SY	3501
Dillard	St. Anthony Ave. 3500	R/R Conc SW 4"	8.00	4.00	3.56	SY	3511
Dillard	St. Anthony Ave. 3600	R/R Conc SW 4"	44.00	4.00	19.56	SY	3601
Dillard	St. Denis 1600	R/R Asph 5.5"	4.00	4.00	1.78	SY	1618
Dillard	St. Denis 1600	R/R Asph 5.5"	3.00	6.00	2.00	SY	1618
Dillard	St. Denis 1600	R/R Asph 5.5"	19.00	26.00	54.89	SY	1640
Dillard	St. Denis 1600	R/R Asph 5.5"	10.00	9.00	10.00	SY	1670
Dillard	St. Denis 1700	R/R Conc SW 4"	10.00	4.00	4.44	SY	1720
Dillard	St. Denis 1700	R/R Asph 5.5"	3.00	3.00	1.00	SY	1720
Dillard	St. Denis 2100	R/R Conc SW 4"	23.00	4.00	10.22	SY	2100
Dillard	St. Denis 2100	R/R Conc SW 4"	24.00	4.00	10.67	SY	2170
Dillard	St. Denis 2100	R/R Conc SW 4"	10.00	4.00	4.44	SY	2124
Dillard	St. Denis 2100	R/R Asph 5.5"	258.00	20.00	573.33	SY	2104 to 2148
Dillard	Stephen Girard 1800	R/R Conc SW 4"	72.00	4.00	32.00	SY	1801
Dillard	Stephen Girard 1800	R/R Conc SW 4"	30.00	4.00	13.33	SY	1888
Dillard	Stephen Girard 1900	R/R Conc Pvmt 8"	9.00	30.00	30.00	SY	1925
Dillard	Stephen Girard 1900	R/R Conc Pvmt 8"	5.00	14.00	7.78	SY	1919
Dillard	Stephen Girard 1900	R/R Conc SW 4"	4.00	4.00	1.78	SY	1913
Dillard	Stephen Girard 2000	R/R Conc SW 4"	74.00	4.00	32.89	SY	Opposite 2018

Dillard

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Dillard	Stephen Girard 2000	R/R Conc SW 4"	12.00	4.00	5.33	SY	2040
Dillard	Stephen Girard 2000	R/R Conc SW 4"	4.00	4.00	1.78	SY	Opposite 2044
Dillard	Stephen Girard 2000	R/R Conc SW 4"	21.00	4.00	9.33	SY	2085
Dillard	Stephen Girard 2100	R/R Conc SW 4"	12.00	4.00	5.33	SY	2120
Dillard	Stephen Girard 2100	R/R Conc SW 4"	68.00	4.00	30.22	SY	2198
Dillard	Stephen Girard 2100	R/R Asph 5.5"	110.00	18.00	220.00	SY	2198
Dillard	Stephen Girard 2100	R/R Asph 5.5"	125.00	6.00	83.33	SY	2190 to 2152
Dillard	Stephen Girard 2100	R/R Conc SW 4"	22.00	4.00	9.78	SY	2119
Dillard	Stephen Girard 2100	R/R Conc SW 4"	17.00	4.00	7.56	SY	2110
Dillard	Stephen Girard 2100	R/R Conc SW 4"	4.00	4.00	1.78	SY	2143
Dillard	Sumpter 1800	R/R Asph 5.5"	6.00	6.00	4.00	SY	1888
Dillard	Sumpter 1800	R/R Conc SW 4"	18.00	4.00	8.00	SY	1888
Dillard	Sumpter 1800	R/R Conc SW 4"	15.00	4.00	6.67	SY	1850
Dillard	Sumpter 1800	R/R Conc SW 4"	93.00	4.00	41.33	SY	1811 to 1837
Dillard	Sumpter 1800	R/R Conc SW 4"	10.00	4.00	4.44	SY	1810
Dillard	Sumpter 1900	R/R Conc SW 4"	64.00	4.00	28.44	SY	1900
Dillard	Sumpter 1900	R/R Conc SW 4"	26.00	4.00	11.56	SY	1938
Dillard	Sumpter 1900	R/R Conc SW 4"	28.00	4.00	12.44	SY	1961
Dillard	Sumpter 1900	R/R Conc SW 4"	71.00	4.00	31.56	SY	1901
Dillard	Sumpter 2000	R/R Conc SW 4"	25.00	4.00	11.11	SY	2046
Dillard	Sumpter 2000	R/R Conc SW 4"	21.00	4.00	9.33	SY	2038
Dillard	Sumpter 2000	R/R Conc SW 4"	20.00	4.00	8.89	SY	2088
Dillard	Sumpter 2000	R/R Conc SW 4"	41.00	4.00	18.22	SY	2020
Dillard	Sumpter 2000	R/R Conc SW 4"	30.00	4.00	13.33	SY	2000
Dillard	Sumpter 2100	R/R Conc SW 4"	31.00	4.00	13.78	SY	2140
Dillard	Sumpter 2100	R/R Conc SW 4"	46.00	4.00	20.44	SY	2188
Dillard	Sumpter 2100	R/R Conc SW 4"	29.00	4.00	12.89	SY	2160
Dillard	Sumpter 2100	R/R Conc SW 4"	10.00	4.00	4.44	SY	2176
Dillard	Sumpter 2100	R/R Conc SW 4"	16.00	4.00	7.11	SY	2100
Dillard	Sumpter 2100	R/R Asph 5.5"	33.00	10.00	36.67	SY	2137
Dillard	Touro 3300	R/R Asph 5.5"	25.00	25.00	69.44	SY	3301
Dillard	Touro 3300	R/R Conc Pvmt 8"	22.00	76.00	185.78	SY	Intersection at Humanity
Dillard	Touro 3400	R/R Conc SW 4"	10.00	4.00	4.44	SY	3496
Dillard	Touro 3500	R/R Conc Pvmt 8"	5.00	6.00	3.33	SY	Intersection at Sere
Dillard	Touro 3500	R/R Conc SW 4"	11.00	4.00	4.89	SY	3515
Dillard	Touro 3600	R/R Conc SW 4"	12.00	4.00	5.33	SY	3614

Dillard

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Dillard	Touro 3600	R/R Conc SW 4"	20.00	4.00	8.89	SY	3640
Dillard	Touro 3700	R/R AspH 5.5"	30.00	15.00	50.00	SY	Intersection at Milton
Dillard	Touro 3900	R/R Conc SW 4"	38.00	5.00	21.11	SY	3915
Dillard	Touro 3900	R/R AspH 5.5"	94.00	10.00	104.44	SY	3909 to 3901
Dillard	Touro 3900	R/R AspH 5.5"	65.00	7.00	50.56	SY	3937
Dillard	Touro 3900	R/R AspH 5.5"	40.00	10.00	44.44	SY	3938
Dillard	Touro 3900	R/R AspH 5.5"	98.00	12.00	130.67	SY	3933 to 3915
Dillard	Touro 3900	R/R AspH 5.5"	38.00	12.00	50.67	SY	3915
Dillard	Touro 4000	R/R Conc SW 4"	49.00	5.00	27.22	SY	Opposite 4035
Dillard	Touro 4000	R/R AspH 5.5"	21.00	14.00	32.67	SY	4035
Dillard	Touro 4200	R/R Conc SW 4"	24.00	4.00	10.67	SY	4235
Dillard	Touro 4200	R/R Conc SW 4"	47.00	4.00	20.89	SY	4226 to 4200
Dillard	Touro 4300	R/R Conc SW 4"	20.00	4.00	8.89	SY	4334
Dillard	Touro 4300	R/R Conc SW 4"	33.00	4.00	14.67	SY	4304
Dillard	Touro 4400	R/R Conc SW 4"	10.00	4.00	4.44	SY	4400
Dillard	Touro 4400	R/R Conc SW 4"	20.00	4.00	8.89	SY	4440
Dillard	Touro 4500	R/R Conc SW 4"	32.00	4.00	14.22	SY	4519
Dillard	Touro 4500	R/R Conc SW 4"	36.00	4.00	16.00	SY	4507
Dillard	Touro 4500	R/R Conc SW 4"	8.00	4.00	3.56	SY	4505
Dillard	Touro 4500	R/R Conc SW 4"	9.00	4.00	4.00	SY	4531
Dillard	Touro 4600	R/R AspH 5.5"	6.00	14.00	9.33	SY	Intersection at Sumpter
Dillard	Touro 4600	R/R Conc SW 4"	16.00	4.00	7.11	SY	4611 to 4605
Dillard	Touro 4600	R/R Conc SW 4"	31.00	4.00	13.78	SY	4634
Dillard	Touro 4700	R/R AspH 5.5"	6.00	6.00	4.00	SY	4721
Dillard	Touro 4700	R/R Conc SW 4"	32.00	4.00	14.22	SY	4730
Dillard	Touro 4700	R/R Conc SW 4"	20.00	4.00	8.89	SY	4701
Dillard	Touro 4700	R/R AspH 5.5"	14.00	8.00	12.44	SY	Intersection at Carnot
Dillard	Touro 4800	R/R AspH 5.5"	24.00	4.00	10.67	SY	4801
Dillard	Van Dr 4200	R/R Conc SW 4"	24.00	4.00	10.67	SY	4206
Dillard	Van Dr 4200	R/R Conc SW 4"	53.00	4.00	23.56	SY	4217 to 4219
Dillard	Van Dr 4200	R/R Conc SW 4"	18.00	4.00	8.00	SY	4208
Dillard	Van Dr 4200	R/R AspH 5.5"	13.00	7.00	10.11	SY	4212
Dillard	Van Dr 4200	R/R Conc SW 4"	29.00	4.00	12.89	SY	4212
Dillard	Van Dr. 4300	R/R Conc SW 4"	20.00	4.00	8.89	SY	4320
Dillard	Van Dr. 4300	R/R AspH 5.5"	9.00	24.00	24.00	SY	4310
Dillard	Van Dr. 4300	R/R Conc SW 4"	10.00	4.00	4.44	SY	4361

Dillard

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Dillard	Van Dr. 4300	R/R Conc SW 4"	43.00	4.00	19.11	SY	4321
Dillard	Van Dr. 4300	R/R AspH 5.5"	12.00	9.00	12.00	SY	4312
Dillard	Van Dr. 4300	R/R Conc SW 4"	48.00	4.00	21.33	SY	4319
Dillard	Van Dr. 4300	R/R Conc SW 4"	23.00	4.00	10.22	SY	4304
Dillard	Van Dr. 4300	R/R Conc SW 4"	20.00	4.00	8.89	SY	4355
Dillard	Van Dr. 4300	R/R AspH 5.5"	9.00	9.00	9.00	SY	4307
Dillard	Virgil Blvd 3700	R/R Conc SW 4"	39.00	4.00	17.33	SY	Opposite 3772
Dillard	Virgil Blvd 3700	R/R AspH 5.5"	14.00	25.00	38.89	SY	3772
Dillard	Virgil Blvd 3700	R/R Conc SW 4"	32.00	4.00	14.22	SY	3766 to 3760
Dillard	Virgil Blvd 3700	R/R Conc SW 4"	12.00	4.00	5.33	SY	3743
Dillard	Virgil Blvd 3700	R/R AspH 5.5"	14.00	12.00	18.67	SY	3730
Dillard	Virgil Blvd 3700	R/R Conc SW 4"	39.00	4.00	17.33	SY	3748
Dillard	Virgil Blvd 3700	R/R Conc SW 4"	16.00	4.00	7.11	SY	3716
Dillard	Virgil Blvd 3700	R/R Conc SW 4"	5.00	4.00	2.22	SY	3730
Dillard	Virgil Blvd. 3800	R/R Conc SW 4"	42.00	4.00	18.67	SY	3824 to 3800
Dillard	Virgil Blvd. 3800	R/R Conc SW 4"	16.00	4.00	7.11	SY	3849
Dillard	Virgil Blvd. 3800	R/R Conc SW 4"	30.00	4.00	13.33	SY	3836 to 3830
Dillard	Virgil Blvd. 3800	R/R Conc SW 4"	16.00	4.00	7.11	SY	3867
Dillard	Virgil Blvd. 3900	R/R Conc SW 4"	62.00	4.00	27.56	SY	3910 to 3904
Dillard	Virgil Blvd. 3900	R/R Conc SW 4"	10.00	4.00	4.44	SY	3903
Dillard	Virgil Blvd. 3900	R/R Conc SW 4"	22.00	4.00	9.78	SY	3911
Dillard	Virgil Blvd. 3900	R/R Conc SW 4"	25.00	4.00	11.11	SY	3919 to 3913
Dillard	Virgil Blvd. 3900	R/R Conc SW 4"	39.00	4.00	17.33	SY	3912
Dillard	Virgil Blvd. 3900	R/R Conc DW 6"	11.00	12.00	14.67	SY	399 to 3913
Dillard	Virgil Blvd. 4000	R/R Conc SW 4"	25.00	4.00	11.11	SY	4040
Dillard	Virgil Blvd. 4000	R/R Conc SW 4"	56.00	4.00	24.89	SY	4031 to 4019
Dillard	Wallace Dr 400	R/R Conc SW 4"	15.00	4.00	6.67	SY	418
Dillard	Wallace Dr 400	R/R Conc SW 4"	17.00	4.00	7.56	SY	411
Dillard	Wallace Dr 400	R/R Conc SW 4"	20.00	4.00	8.89	SY	417
Dillard	Wallace Dr 400	R/R Curb	3.00	0.00	3.00	LF	418
Dillard	Wallace Dr 400	R/R Conc SW 4"	15.00	4.00	6.67	SY	405
Dillard	Wallace Dr. 300	R/R Conc SW 4"	25.00	4.00	11.11	SY	306 to 304
Dillard	Wallace Dr. 300	R/R Conc SW 4"	5.00	4.00	2.22	SY	312
Dillard	Wallace Dr. 300	R/R Conc SW 4"	20.00	4.00	8.89	SY	302
Dillard	Wallace Dr. 300	R/R Conc SW 4"	22.00	4.00	9.78	SY	328 to 326
Dillard	Wallace Dr. 500	R/R Conc SW 4"	20.00	4.00	8.89	SY	526

Dillard

Neighborhood	Address in PW	Repair Type	Length (ft)	Width (ft)	Qty	Unit	Damage Address
Dillard	Wallace Dr. 500	R/R Conc SW 4"	44.00	4.00	19.56	SY	504 to 502
Dillard	Wallace Dr. 500	R/R Conc SW 4"	15.00	4.00	6.67	SY	509
Dillard	Wallace Dr. 500	HC Ramp @ Intersection	12.00	12.00	16.00	SY	Intersection at Stephen Girard
Dillard	Wallace Dr. 500	R/R Conc Pvmt 8"	3.00	10.00	3.33	SY	Intersection at Stephen Girard
Dillard	Wallace Dr. 500	R/R Conc SW 4"	21.00	4.00	9.33	SY	506
Dillard	Wallace Dr. 500	R/R Conc SW 4"	12.00	4.00	5.33	SY	Intersection at Stephen Girard
Dillard	Warrington Dr 400	R/R Conc SW 4"	16.00	4.00	7.11	SY	Intersection at Stephen Girard
Dillard	Warrington Dr 400	R/R Conc SW 4"	8.00	4.00	3.56	SY	417
Dillard	Warrington Dr 400	HC Ramp @ Intersection	12.00	12.00	16.00	SY	Intersection at Stephen Girard
Dillard	Warrington Dr 4800	R/R Conc SW 4"	12.00	4.00	5.33	SY	4821
Dillard	Warrington Dr 500	R/R Conc SW 4"	47.00	4.00	20.89	SY	511
Dillard	Warrington Dr 500	R/R Conc SW 4"	20.00	4.00	8.89	SY	503 to 505
Dillard	Warrington Dr 500	R/R Conc SW 4"	26.00	4.00	11.56	SY	536 to 538
Dillard	Warrington Dr 500	R/R Conc SW 4"	14.00	4.00	6.22	SY	537
Dillard	Warrington Dr 500	R/R Conc SW 4"	16.00	4.00	7.11	SY	548
Dillard	Warrington Dr 500	R/R Conc SW 4"	30.00	4.00	13.33	SY	539
Dillard	Warrington Dr 500	R/R Conc SW 4"	16.00	4.00	7.11	SY	509
Dillard	Warrington Dr 500	R/R Conc SW 4"	38.00	4.00	16.89	SY	550
Dillard	Warrington Dr 500	R/R Conc SW 4"	40.00	4.00	17.78	SY	556
Dillard	Warrington Dr 500	R/R Conc SW 4"	52.00	4.00	23.11	SY	512 to 514
Dillard	Warrington Dr 500	R/R Conc SW 4"	13.00	4.00	5.78	SY	516
Dillard	Warrington Dr 500	R/R Conc SW 4"	15.00	4.00	6.67	SY	519
Dillard	Warrington Dr. 200	R/R Conc SW 4"	20.00	4.00	8.89	SY	212
Dillard	Warrington Dr. 200	R/R Conc SW 4"	38.00	4.00	16.89	SY	216
Dillard	Warrington Dr. 200	R/R Conc SW 4"	22.00	4.00	9.78	SY	220
Dillard	Warrington Dr. 300	R/R Conc SW 4"	20.00	4.00	8.89	SY	318
Dillard	Warrington Dr. 300	R/R Conc Pvmt 8"	21.00	27.00	63.00	SY	326
Dillard	Warrington Dr. 300	R/R Conc SW 4"	14.00	4.00	6.22	SY	327
Dillard	Warrington Dr. 300	R/R Conc SW 4"	20.00	4.00	8.89	SY	326
Dillard	Warrington Dr. 300	R/R Conc SW 4"	12.00	4.00	5.33	SY	321
Dillard	Warrington Dr. 300	R/R Conc Pvmt 8"	18.00	11.00	22.00	SY	306
Dillard	Warrington Dr. 300	R/R Conc Pvmt 8"	5.00	6.00	3.33	SY	312
Dillard	Warrington Dr. 4700	R/R Conc SW 4"	58.00	4.00	25.78	SY	4728